# **UNCLASSIFIED**

AD NUMBER
AD907152
NEW LIMITATION CHANGE
TO Approved for public release, distribution unlimited
FROM Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; 01 DEC 1972. Other requests shall be referred to Air Force Weapons Lab., Kirtland AFB, NM.
AUTHORITY
CEEDO USAF 1tr 29 Jun 1977

THIS REPORT HAS BEEN DELIMITED AND CLEARED FOR PUBLIC RELEASE UNDER DOD DIRECTIVE 5200.20 AND NO RESTRICTIONS ARE IMPOSED UPON ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

### PAVEMENT CRATERING STUDIES

Asbjorn Kvammen, Jr. Raman Pichumani
The Eric H. Wang Civil Engineering Research Facility
University of New Mexico

James L. Dick, Jr.
Capt. USAF
Air Force Weapons Laboratory

TECHNICAL REPORT NO. AFWL-TR-72-61


December 1972



AIR FORCE WEAPONS LABORATORY
Air Force Systems Command
Kirtland Air Force Base
New Mexico

Distribution limited to U.S. Government agencies only because of test and evaluation (1 Dec 72). Other requests for this document must be referred to AFWL (DEZ), Kirtland AFB, NM.

# DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

AIR FORCE WEAPONS LABORATORY Air Force Systems Command Kirtland Air Force Base New Mexico 87117

When US Government drawings, specifications, or other data are used for any purpose other than a definitely related Government procurement operation, the Government thereby incurs no responsibility nor any obligation whatsoever, and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise, as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

DO NOT RETURN THIS COPY, RETAIN OR DESTROY.

### PAVEMENT CRATERING STUDIES

Asbjorn Kvammen, Jr.

Raman Pichumani

The Eric H. Wang Civil Engineering Research Facility University of New Mexico

James L. Dick, Jr. Capt. USAF

Air Force Weapons Laboratory

TECHNICAL REPORT NO. AFWL-TR-72-61

Distribution limited to U.S. Government agencies only because of test and evaluation (1 Dec 72). Other requests for this document must be referred to AFWL (DEZ), Kirtland AFB, NM.

AFWL-TR-72-61

### FOREWORD

This report was prepared by the Eric II. Wang Civil Engineering Research Facility, University of New Mexico, Albuquerque, New Mexico, under Contract F29601-72-C-0024. The research was performed under Program Element 63723F, Project 683M, Subtask 4.6.110.

Inclusive dates of research were January 1971 through January 1972. The report was submitted 10 November 1972 by the Air Force Weapons Laboratory Project Officer, Captain James L. Dick (DEZ-S).

This technical report has been reviewed and is approved.

Sick, In

JAMES L. DICK

Captain, USAF Project Officer

OREN G. STROM

Lt Colonel, USAF

Chief, Aerospace Facilities Branch

Milliam B. Liddicoet WILLIAM B. LIDDICOET

Colonel, USAF

Chief, Civil Engineering Research

Division

# ABSTRACT (Distribution Limitation Statement B)

the objectives of this research effort were twofold: (1) to define the damage to airfield pavement systems caused by a wide range of C-4 Charges and bombs when detonated at various depths below the pavement surface (i.e., determine the extent of damage expected from these explosives), and (2) to investigate the feasibility of scaling pavement systems and explosive in order to more economically study cratering effects on different pavement systems. The first objective was implemented by a series of tests using 5, 15, and 25-1b C-4 charges placed at various depths under pavement surfaces in two abandoned airfields (Fort Summer and Hays) and three sizes of bombs at the Hays test site. Damage such as the repair volumes, true crater depths, etc., were plotted as a function of charge size and depth-of-burst. Three types of craters were (1) shallow depth-of-burst craters of hemispherical shape, (2) deep depth-of-burst craters with no apparent crater and little ejecta, and (3) intermediate depth-of-burst craters exhibiting some of the characteristics of both the shallow and the deep craters. The crater dimensions from Fort Summer (sandy silt subgrade) were, in general, smaller than those from Hays (clay subgrade) for all C 4 charges. A similitude analysis was conducted using the test data from the C-4 charges (Hays) to ascertain if a scaling factor or a distortion factor could be determined. The study revealed that the scaling factor varied widely when scaling the maximum damage depth-of-burst, the radius of the crater at the surface, and the crater volumes. To accomplish the second objective, small-scale tests were conducted modeling the full-scale experimental tests performed at CERF in 1909. This study also indicated variations in scaling factors.

### CONTENTS

Section		Page
I	INTRODUCTION	1
II	TEST SITES	3
III	EXPLOSIVES	8
IV	CRATER PARAMETERS	10
v	TEST PROCEDURES	13
VI	FULL-SCALE FIELD TEST DATA	17
	1. Crater Types	17
	2. Fort Summer Test Results	17
	3. Hays Test Results	25
VII	DATA ANALYSIS	56
	1. Fort Summer Data	56
	2. Hays Data	59
VIII	SMALL-SCALE MODEL FEASIBILITY STUDY	84
	1. Literature Survey	84
	2. Preliminary Model Study	86
IX	CONCLUSIONS AND RECOMMENDATIONS	96
	Appendixes:	
	I Fort Sumner Subsurface Exploration Data	99
	II Hays Subsurface Exploration Data	109
	III Fort Sumner Crater Data	118
	IV Hays Crater Data	132
	V Model Study Data	164
	References	1.73

### ILLUSTRATIONS

Eimpo	1000010112111	Page
Figure	D. A. C. annua (Part City)	4
1	Fort Summer Test Site	5
2	Fort Summer Test Section	6
3	Hays Test Site	_
4	Havs Test Section	7
5	C-4 Charges Used at Fort Summer and Hays	8
6	Bombs Used at Hays	9
7	Typical Crater	11
8	Typical Crack Pattern of Concrete with Joints	12
9	2.5-1b C-4 Shape Charge	13
10	Auger and Typical C-4 Charge	14
1.1	Placement of 500-1b Bomb	14
12	Crater Types	18
13	True Soil and Concrete (rater Volumes versus Depth-of-Burst for 5-1b Charge (Fort Sumner)	20
14	Crater Radii versus Depth-of-Burst for 5-1b Charge (Fort Summer)	20
15	Crater from Detonation of 5-1b Charge (Fort Summer)	21
16	True Soil and Concrete Crater Volumes versus Depth-of-Burst for 15-1b Charge (Fort Summer)	22
17	Crater Radii versus Depth-of Burst for 15-1b Charge (Fort Summer)	22
18	Craters from Detonation of 15-1b Charge (Fort Summer)	23
19	True Soil and Concrete Crater Volumes versus Depth-of-Burst for 25-1b Charge (Fort Sumner)	26
20	Crater Radii versus Depth-of-Bur.t for 25-1b Charge (Fort Summer)	26
21	Crater from Detonation of 25-1b Charge (Fort Sumner)	27
22	True Soil and Concrete Crater Volumes versus Depth-of-Burst	28

# ILLUSTRATIONS (Cont'd)

Figure		Page
23	Crater Radii versus Depth-of-Burst for 5-1b Charge Under 8-Inch-Thick Concrete (Hays)	28
24	Craters from Detonation of 5-1b Charge Under 8-Inch- Thick Concrete (Hays)	30
25	True Soil and Concrete Crater Volumes versus Depth-of-Burst for 5-lb Charge Under 11-Inch-Thick Concrete (Hays)	32
26	Crater Radii versus Depth-of-Burst for 5-1b Charge Under 11-Inch-Thick Concrete (Hays)	32
27	True Soil and Concrete Crater Volumes versus Depth-of-Burst for 15-lb Charge Under 8-Inch-Thick Concrete (Hays)	33
28	Crater Radii versus Depth-of-Burst for 15-1b Charge Under 8-Inch-Thick Concrete (Hays)	33
29	Craters from Detonation of 15-1b Charge Under 8-Inch- Thick Concrete (Hays)	34
30	True Soil and Concrete Crater Volumes versus Depth-of-Burst for 15-lb Charge Under 11-Inch-Thick Concrete (Hays)	37
31	Crater Radii versus Depth-of-Burst for 15-lb Charge Under 11-Inch-Thick Concrete (Hays)	37
32	Craters from Detonation of 15-1b Charge Under 11-Inch- Thick Concrete (Hays)	39
33	True Soil and Concrete Crater Volumes versus Depth-of-Burst for 25-1b Charge Under 8-Inch-Thick Concrete (Hays)	40
34	Crater Radii versus Depth-of-Burst for 25-lb Charge Under 8-Inch-Thick Concrete (Hays)	40
35	Craters from Detonation of 25-1b Charge Under 8-Inch- Thick Concrete (Hays)	41
36	True Soil and Concrete Crater Volumes versus Depth-of-Burst for MK-81 Romb (Hays)	44
37	Crater Radii versus Depth-of-Burst for MK-81 Bomb (Hays)	44
38	Craters from Detonation of MK-81 Bomb (Hays)	45
39	True Soil and Concrete Crater Volumes versus Depth-of-Burst for MK-82 Bomb (Hays)	48
40	Crater Radii versus Depth-of-Burst for MK-82 Bomb (Hays)	48

# ILLUSTRATIONS (Cont'd)

Figure		Page
41	Craters from Detonation of MK-82 Bomb (Hays)	49
42	True Soil and Concrete Crater Volumes versus Depth-of-Burst for M-117 Bomb (Hays)	53
43	Crater Radii versus Depth-of-Burst for M-117 Bomb (Hays)	53
4.1	Craters from Detonation of M-117 Bomb (Mays)	54
45	Crater Damage versus Charge Size (Fort Sumner)	57
46	Ratio of Average Concrete Repair Volume to Average Combined Repair Volume versus C 4 Charge Size (Fort Sumner)	60
47	Area of Concrete to be Removed versus Depth-of-Burst for C-4 Charges (Fort Summer)	61
48	True Crater Depth versus Depth-of-Burst (Fort Sumner)	62
49	Aspect Ratio versus Depth-of-Burst for C-4 Charges (Fort Sumner)	63
50	Crater Damage versus Charge Size (Hays)	65
51	Ratio of Average Concrete Repair Volume to Average Combined Repair Volume versus C-4 Charge Size (Hays)	67
52	Area of Concrete to be Removed versus Depth-of-Burst for C-4 Charges (Hays)	68
53	Aspect Ratio versus Depth-of-Burst for C-4 Charges (Hays)	70
51	Crater Damage versus Bomb Size (Plys)	75
55	Area of Concrete to be Removed versus Depth-of-Burst for Bombs (Hays)	78
56	\pparent Cater Depth versus Depth-of-Burst for Bombs (Hays)	79
57	Ejecta versus Depth-of-Burst for Bombs (Hays)	80
58	Apparent Crater Volume versus Depth-of-Burst for Bombs (Hays)	81
59	True Crate: Depth versus Depth of-Burst for C-4 Charges and Bombs (Hays)	83
60	Full-Scale Rigid Pavement System [after Pichumani (ref. 1)]	87

# ILLUSTRATIONS (Concl'd)

	IDDOOLIGE (**	
Figure		Page
61	Models of Rigid Pavement System	89
62	Location of Borings (Fort Sumner)	100
63	Location of Borings (Hays)	110

# TABLES

Table		Page
I	Summary of Average Damage Quantities for C-4 Charges (Fort Sumner)	19
11	Summary of Average Damage Quantities for C-4 Charges (Hays)	29
111	Summary of Average Damage Quantities for Bombs (Hays)	42
IV	Shallowest and Maximum Damage Depth-of-Burst Data for C-4 Charges (Fort Sumner)	56
V	Shallowest and Maximum Damage Depth-of-Burst Data for C-4 Charges (Hays)	64
VJ	Scaling and Distortion Factors for C-4 Charges (Hays)	73
VII	Shallowest and Maximum Damage Depth-of-Burst Data for Bombs (Hays)	74
VIII	Summary of Apparent Crater Damage for Bombs (Hays)	82
IX	Model Study Test Data	92
X	Summary of True Crater Damage for Model Tests	93
ΙX	Summary of Test Results from Reference 1	95
XH	Computed Scaling Factors from Model Study	95
ИΙК	Soil Test Data (Fort Sumner)	101
XIV	Concrete Test Data (Fort Sumner)	108
XV	Soil Test Data (Hays)	111
XVI	Summary of In-Place Density Tests (Hays)	115
XVTI	Concrete Test Data (Hays)	117
IIIVX	Damage Quantities for C-4 Charges (Fort Sumner)	119
XIX	Damage Quantities for C-4 Charges (Hays)	133
XX	Damage Quantities for Bombs (Hays)	135

# ABBREVIATIONS AND SYMBOLS

С	linear parameter
D	true crater depth
Ec	modulus of elasticity of concrete
$G_{\mathbf{s}}$	specific gravity
Н	apparent crater depth
R	surface crater radius (calculated)
R <sub>2</sub>	crater repair radius (calculated)
R <sub>3</sub>	maximum radius at any depth
V	volune
$R_{\bullet}$	weight of explosive
$f_c^i$	compressive strength of concrete
111	distortion factor
n	scaling factor
w	moisture content
Υ	density of media
$\gamma_{ m d}$	dry soil density

### SECTION I

### INTRODUCTION

### 1. BACKGROUND

Development of expedient techniques for rapidly repairing airfield pavements damaged by small and large weapons has recently acquired great importance. A prerequisite for this development is the proper understanding of the damage parameters of pavement cratering. A preliminary study of these parameters was carried out by the Air Force Weapons Laborator; (AFWL) in conjunction with the University of New Mexico at the Eric H. Wang Civil Engineering Research Facility (CERF) (ref. 1). In this study small cratering charges (1-1/2 lb of C-4 explosive) were used to simulate the BLU-67, an aerially delivered cratering device. These charges were detonated at a constant depth of 30 in. below different pavement systems. The effect of different pavement systems on the resulting craters was studied as well as the effect of detonation under joints and joint intersections.

Subsequent requirements have necessitated an expanded program to test the effects of large charges detonated at various depths below pavement surfaces. Test sites were selected to provide a variation in subgrade and pavement thickness similar to the European theater of operations.

### 2. OBJECTIVES

The first objective of this effort was to define the damage parameters that can be expected from a variety of charges and bombs detonated at various depths below the surface of airfield pavements. These damage parameters are of paramount importance in formulating repair techniques and in designing repair equipment to encompass all possible situations. The effects of the subgrade and pavement thickness on the resulting craters were also of primary concern. The second objective was to determine the feasibility of scaling the damage expected in different pavement systems by varying explosive charges to lower the cost of experimentation.

### APPROACH

To achieve the above mentioned objectives, two parallel research programs were undertaken: (1) full-scale field tests at two abandoned airfields, and

(2) small-scale model studies consisting of a feasibility study, including a literature survey, and a model study of the full-scale field tests. (In this report only the feasibility study of the small-scale models is included. The model study of the full-scale field tests has not been conducted.)

The full-scale field tests consisted of a series of shots with a military plastic explosive (C-4) having a charge weight of 15 lb detonated at 10, 30, 50, 70, 90, and 110 in. below the pavement surface. This initial series was repeated a number of times. After the necessary data were accumulated, the depth-of-burst causing the maximum crater volume was noted. Since the scaling factor for cratering in pavement systems has not yet been determined, cube-root scaling used in general cratering problems was used to calculate the depth-of-burst for the other charges (5- and 25-lb C-4 explosive). Two additional depths-of-burst for both the 5- and 25-lb charges were arbitrarily set at 1/2 and 3/2 of the chosen scaled depth-of-burst. Each of the three depths-of-burst was used three times for a total of nine shots for each of the two charges.

Of critical importance in this research effort was the definition of the range of runway damage developed from the detonation of bombs. To define this damage, three bombs were tested—the Mk-81 (250-1b bomb), the MK-82 (500-1b low-drag bomb), the M-117 (750-1b general purpose bomb). Six of each were tested. The depths-of-burst chosen were calculated from cube-root scaling of the depth-of-burst giving maximum damage from the 25-1b uncased C-4 charge. Subsequent depths-of burst were selected after each cruter was excavated and volumes were calculated.

To achieve the required number of shots dictated by the test plan, a large area of concrete pavement was needed. Construction of a test section with different types of subgrades was prohibitively expensive; therefore, a survey of abandoned airfields was made to find an existing area of pavement that could be utilized for these tests. Only two sites met the requirements. One site, near Hays, Kansas, had a clay subgrade and offered a choice of two pavement thicknesses. The other site, at Fort Summer, New Mexico, had a soil type that was predominantly a silty sand and a pavement thickness different from that of the Hays site pavement.

### SECTION II

### TEST SITES

### 1. FORT SUMNER

The Fort Summer test site, located in the southeastern part of New Mexico, is shown in figure 1. The test section, leased from the city of Fort Summer, was a 75-ft-wide, 1,800-ft-long, 7-in.-thick concrete slab overlying a silty sand subgrade (fig. 2). The pavement consisted of 20-ft-long pads, 10 ft wide, except for the west-side pads which were 15 ft wide.

Before testing, the pads were numbered in sequential order as shown in figure 2.

Laboratory tests of soil samples obtained by subsoil explorations at this site were performed at CERF; concrete specimens obtained by coring some cylinders from the concrete slab were also tested at CERF. The results of these tests are given in appendix I.

### 2. HAYS

The Hays test site, located 18 miles east of Hays, Kansas, is shown in figure 3. The test section (one of the three main runways) was 150 ft wide, 5,600 ft long, and ran in a northeast-southwest direction (fig. 4). Each pad was approximately 20 ft long and 12.5 ft wide. The Portland cement concrete slabs were 11 in. thick for the two center pads and 8 in. thick elsewhere, and rested on a 5-ft-thick organic clay layer. Beneath this layer was a 12-ft-thick silty clay layer overlying 3 ft of sand. Beneath the sand was a 5-to 6-ft-thick shale layer overlying a 6-ft-thick lime sandstone layer which was underlaid by a deep shale layer.

Before testing, the individual concrete pads were numbered in sequential order starting with the pad in the southwest corner (fig. 4). A typical number would be 5/6--the first digit describing the row, the second digit describing the column.

Soil and concrete specimens obtained by subsoil exploration and concrete coring at various points on the test section were tested in the laboratory at CERF; the results of these tests are given in appendix II.




Figure 1. Fort Sumner Test Site






Figure 2. Fort Summer Test Section



Victoria-Pratt Airport

Figure 3. Hays Test Site






Figure 4. Hays Test Section

### SECTION III

### **EXPLOSIVES**

### 1. C-4 CHARGES

Uncased military plastic explosive (C-4) was used in various charge sizes at both Fort Summer and Hays. This explosive, which can be manufactured easily and inexpensively, is a readily workable and stable composition with an explosive energy of approximately 1.3 times that of an equivalent weight of TNT. This explosive was formed into cylindrically shaped charges of 5, 15, and 25 lb and placed in tin cans to prevent damage during placement. Figure 5 shows the C-4 charges used.

Each charge was detonated by two booster detonation caps attached to a length of 175-grain explosive detonation cord. An electric blasting cap was taped to the detonation cord to initiate the explosion.





Figure 5. C-4 Charges Used at Fort Sumner and Hays

### 2. BOMBS

Three bombs were used at the Hays test site in addition to the C-4 charges. They were the MK-81 (250-1b bomb), the MK-82 (500-1b low-drag bomb), and the M-117 (750-1b general purpose bomb). Figure 6 shows these three bomb types.



MK-81 (250-1b Bomb) Explosive Weight: 100 1b

MK-82 (500-1b Bomb) Explosive Weight: 192 1b

M-117 (750-1b Bomb) Explosive Weight: 386 1b




Figure 6. Bombs Used at Hays

### SECTION IV

### CRATER PARAMETERS

Figure 7a illustrates a typical crater caused by subsurface detonation of explosive charges in a pavement system. The crater parameters that were actually recorded in the tests conducted in this research are shown in figure 7 and are described below.

aoser.	roca noion.	
(1)	True Crater Depth (D)	Depth from bottom of true crater to original concrete surface.
(2)	Apparent Crater Depth (II)	Depth from top of fallback material at center of crater to original concrete surface.
(3)	Depth-of-Burst (DOB)	Depth from original concrete surface to center of charge.
(4)	Maximum Damage Depth-of- Burst (MDDOB)	Depth-of-burst yielding a maximum damage quantity.
(5)	Ejecta	All material thrown out o. crater.
(6)	Concrete Crater Volume	Volume of concrete thrown out (computed from surface area of crater measured).
(7)	Concrete Repair Volume	Volume of total concrete to be repaired (calculated from crack pattern).
(8)	True Soil Crater Volume	Volume of soil crater from below the concrete slab to true crater wall.
(9)	Apparent Crater Volume	Volume of crater from original concrete surface to apparent crater wall.
(10)	True Soil Crater and Concrete Crater Volume	Sum of (6) and (8).
(11)	True Soil Crater and Concrete Repair Volume	Sum of (7) and (8).
(12)	Calculated Surface Crater Radius (R <sub>1</sub> )	An empirical number calculated from
		$\sqrt{\frac{\text{Concrete Crater Volume}}{\pi(\text{Concrete Thickness})}}$



(a) Apparent Crater




Figure 7. Typical Crater

(13) Calculated Concrete Repair Radius (R<sub>2</sub>) An empirical number calculated from

 $\sqrt{\frac{\text{Concrete Repair Volume}}{\pi(\text{Concrete Thickness})}}$ 

visualizing the utmost circumferential crack pattern in concrete to be repaired.

Area of concrete to be removed due to heave and cracks.

Maximum radius of true crater at any depth.

Ratio of true crater depth to surface crater radius.

(14)  $\pi(R_2^2 - R_1^2)$ 

(15) Maximum Radius (R<sub>3</sub>)

(16) Aspect Ratio, D/R

Crack patterns of concrete damaged by small charges were irregular (i.e., not symmetrical) because of the effects of the joints (fig. 8). However, as the charge size increased, the effects of the joints decreased and the surface craters became symmetrical about the center of the crater. To define an average surface crater radius from the irregularly shaped crack pattern, the surface crater radius, R<sub>1</sub>, and the concrete repair radius, R<sub>2</sub>, were defined empirically as in items (12) and (13).




Figure 8. Typical Crack Pattern of Concrete with Joints

### SECTION V

### TEST PROCEDURES

The testing procedures were essentially the same at both test sites. The test pads were chosen on the basis of uniformity and lack of damage.

### 1. PLACEMENT OF EXPLOSIVES

The C-4 charges and the bombs were placed at the proper depth by detonating a 2.5-lb C-4 shape charge (fig. 9) on the pavement surface to provide access to the underlying soil. An auger was then used to drill a hole the appropriate diameter of the charge or bomb being placed and to the depth desired. The charge or bomb was then lowered into the auger hole. All depths-of-burst were measured from the center of the charge to the concrete surface. Figure 10 shows the auger and a typical C-4 charge, and figure 11 shows the placement of a 500-lb bomb.




Figure 9. 2.5-1b C-4 Shape Charge




Figure 10. Auger and Typical C-4 Charge




Figure 11. Placement of 500-1b Bomb

### MEASUREMENTS

High-speed motion pictures at 500 and 1,500 frames per second recorded each event. Subsequent examination of the films indicates the occurrence of verting, with considerable pressure being released via the access hole through which the explosives and bombs had been placed. An initial shock-induced motion was visible on the concrete surface coincident with the initiation of venting from the access hole in all craters.

For types of craters created at shallow and intermediate depths-of-burst, pavement response to the detonation was the rapid ejection of concrete from the original curtace. It was assumed that this mode of ejection resulted from a spherically shaped shock wave hitting the under-surface of the pavement. Hence, the area of concrete ejected directly above the explosive was circular in shape. As the spherically shaped shock wave expanded, the size of the ejected concentric rings was enlarged. This was accompanied by the formation of radial cracks in the surrounding slabs. The process of ejecting concentric rings of concrete continued up to a point where the shock wave was sufficiently attenuated. In most cases the last concentric ring was heaved and broken off, but not ejected, from the surrounding undamaged concrete. No visible damage to the concrete was noted beyond this point.

For types of craters created by deep depths-of-burst, which were contained within the soil medium, no concrete ejecta was visible. However, examination of the pavement after the event revealed upheaval and radial cracks.

### a. C-4 Charges

Preshot elevation measurements were taken at the center and corners of all test pads at Fort Summer. Postshot elevation measurements were taken at those points remaining on the pads after detonation and on the crater edge in the north-south and east-west directions.

At Hays, a grid system with 1-ft squares was laid out on the pad selected for testing and on the adjoining pads. For the smaller shots, preshot elevation measurements were taken on a 2 ft-square grid to minimize the number of data points. Postshot elevation measurements were taken at 1-ft intervals on those points still remaining on the pads after detonation.

Other data collected after the initial elevation measurements were made depended on the type of crater that was formed. All craters were excavated to determine the true crater depth. True crater diameters were measured at 2-in. intervals along the vertical axis of the crater from the bottom up. Of prime importance was the accurate measurement and determination of the damaged area of concrete. The crater wall was relatively easy to find since a hard black coating existed beneath the loose fallback material. Volumes were then determined by using the elevation data. (The crater was assumed to be axisymmetric for ease of computation.)

### b. Bombs

Changes in elevation were measured every 10 ft on lines emanating horizontally from the point of detonation at 45-degree intervals (fig. 4). The elevations were again recorded on points remaining after the shot to determine the amount of heave. In addition, the elevations of the fallback material were recorded in the north-south and east-west directions. Ejecta was then removed from the concrete surface and the crack pattern of the concrete was sketched. The volume of concrete thrown out was then calculated. The crater was excavated by digging a trench within the crater to the crater wall and then following the wall contour, using a hand shovel, up the sides to a height at which the wall disappeared. The crater diameters were determined in the same manner as for the C-4 charges except that vertical measurements at 6-in, intervals instead of 2-in, intervals were taken.

### SECTION VI

### FULL-SCALE FIELD TEST DATA

### CRATER TYPES

Visual observation of the craters in the field revealed that there were three types of craters caused by the C-4 charges at different depths-of-burst. These are illustrated in figure 12.

Type I craters (shallow depth-of-burst) were approximately hemispherical in shape; the pavement beyond the crater was not appreciably heaved or cracked; and the ejecta was widely scattered with small concrete pieces, some of which measured a maximum 2 ft.

In type III craters (deep depth-of-burst) no apparent crater was found; however, a cavity was found in the subgrade; the overlying concrete slab was extensively heaved with the resultant radial cracks creating huge wedge-shaped concrete pieces; and there was very little ejecta.

Type II craters (intermediate depth-of-burst) exhibited some of the characteristics of both types I and III; the apparent crater was conical in shape, while the true crater had a bulb at the bottom and the frustum of a cone at the top, and the ejecta was of intermediate size (between that of types I and III). Similar crater classifications can be seen in reference 2.

### 2. FORT SUMNER TEST RESULTS

Appendix III lists the crater parameters of all the Fort Sumner shots and shows the cross-sectional elevations of the individual craters. Average values of the crater parameters for the three C-4 charge sizes are summarized in table I.

### a. 5-1b Charge

Type II craters were noted for depths-of-burst of 20 in. and shallower, type III craters were noted for depths-of-burst of 40 in. and deeper, and type III craters were noted at a 33-in. depth-of-burst (table I).

True soil and concrete crater volumes versus depth-of-burst are plotted in figure 13, and crater radii  $(R_1, R_2, and R_3)$  versus depth-of-burst are plotted in figure 14. The maximum damage depth-of-burst for all crater volumes




Figure 12. Crater Types

SUMBARY OF ATTRAGE DAMAGE QUANTITIES FOR C-4 CHARGES (FORT SUMBER) Table I

-(k² - k²), ft?		180 164 153 200 199	200 200	1.5 *	185 294 186	150 540 200	237 282 295	
	a/1		1.27 1.04 1.20 12.10 8.62	12.65	0.95	0.03	15.41 22.38	0.89 1.28 **
ئ	~	<u>.</u> ۳	2.56 5.42 5.90 1.72	1.50	5.90	6.58	2.28	6.27 6.70 **
Radius, ft	~	۳,	7.99 7.99 7.99 7.99	7.99	8.45	11.70	10.45 7.99	10.71 11.61 11.32
	<u>"</u>	. <b>-</b> -	0.39 0.58 0.58	0.50	5.90 5.86		0.74	6.27 5.70 5.86
	Crater Depth (D),	2	10 10 14 10 10 10 10 10 10 10 10 10 10 10 10 10	5.85 6.35	5.64		8.95 20.8	5.58 8.55 **
		Керан	2.4.5.2.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.	80 08	*	3.55 1.55 1.55 1.55 1.55 1.55 1.55 1.55	173	556 470 **
, <del>v</del>	Concrete and I'me Soil	(Later	842 USE	15	8. 5. 1.	123 P	<u></u> 273	19° 300 **
loltwe, ft	Ine	Crater	87.42.5	712	653	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		124 717 **
ì	ote	kepa, 1	22222	11	); * ;	. [5]	200 117	32.5
	Cenc F	( rater	11.12.0 5.62.9 5.62.95	7:0 2:0	% t. 0	80.88	0.77	S3 53
Pon+	Pepti -oif- burst, in.		L 288348	00	10 50	5000	90 110	54 68 105
Clarge Size, IF		ហ			15		25	

Toncrete thickness was 7 in. for all tests. The concrete volume of one slab, 20 ft x 10 ft, was 117 ft  $^3$ . # Data lost.
\*\*
Imable to excavate crater.




Figure 13. True Soil and Concrete Crater Volumes versus Depth-of-Burst for 5-1b Charge (Fort Sumner)





Figure 14. Crater Radii versus Depth-of-Burst for 5-1b Charge (Fort Sumner)

and crater radius  $R_3$  for the type II crater was 33 in. A crater caused by the detonation of a 5-1b charge is shown in figure 15.

Varying the depth-of-burst affected the concrete crater volumes (i.e., the concrete thrown out). However, regardless of the depth-of-burst, replacement of the entire damaged concrete pads would be necessary because of the cracking and upheaval of the concrete. Varying the depth-of-burst within the test range changed the combined concrete repair and true soil crater volume from 132 to 159 ft<sup>3</sup> (a change of only 20 percent). The average concrete repair volume was approximately 83 percent of the average combined volume and was, therefore, the more significant damage parameter.

### b. 15-1b Charge

The same graphs were plotted for the 15-1b charges as for the 5-1b charges and are shown in figures 16 and 17. The maximum damage depth-of-burst was found to be 70 in. for all crater quantities except for the concrete repair volume which was 50 in. Craters caused by the detonation of a 15-1b charge are shown in figure 18.



Shot 36 17-Inch Depth-of-Burst

Figure 15. Crater from Detonation of 5-lb Charge (Fort Sumner)




Figure 16. True Soil and Concrete Crater Volumes versus Depth-of-Burst for 15-1b Charge (Fort Sumner)





Figure 17. Crater Radii versus Depth-of-Burst for 15-1b Charge (Fort Sumner)



Before Excavation

10-Inch Depth-of-Burst



Before Excavation

Shot 19

Figure 18. Craters from Detonation of 15-1b Charge (Fort Summer)



Before Excavation
70-Inch Depth-of-Burst



Shot 12 110-Inch Depth-of-Burst

Figure 18---Concluded

Varying the depth-of-burst from 10 to 110 in. affected both the concrete crater volume and the concrete repair volume. In this case, an average of one and one-half pads were damaged. Furthermore, by selecting the depth-of-burst so as to maximize damage to the concrete, slightly more than two pads were affected. The combined concrete repair and true soil crater volume varied from 178 to 479 ft<sup>3</sup> (an increase of about 169 percent) within the depth-of-burst range tested. The average concrete repair volume was approximately 59 percent of the average total combined volume.

### c. 25-1b Charge

Figures 19 and 20 show the same graphs as previously plotted for the 5-lb and 15-lb charges. Since the subgrade at Fort Summer consisted mostly of silty sand, the crater walls at depths-of-burst greater than 68 in. collapsed; hence, the true soil crater parameters could not be accurately measured for the 103-in. depth-of-burst. However, the maximum damage depth-of-burst for the concrete crater and the concrete repair volumes was 68 in. (fig. 19). A crater caused by the detonation of a 25-lb charge is shown in figure 21.

For the three depths-of-burst (34, 68, and 103 in.) tested, the concrete crater volumes did not vary by more than 14 percent. The average number of concrete pads damaged in this case was two. By selecting the depth-of-burst so as to maximize damage to the concrete, slightly more than two pads were affected. For the 34-in. depth-of-burst, the total repair volume was 356 ft<sup>3</sup>; for the 68-in. depth-of-burst, the total repair volume was 470 ft<sup>3</sup> (an increase of 32 percent). The average concrete repair volume was about 56 percent of the average total combined volume for these two depths-of-burst.

#### 3. HAYS TEST RESULTS

From the recorded data, plots were made of each crater to compute the concrete crater volume, the concrete repair volume, the true soil crater volume, and the combined volumes. In addition, the true crater depth, the surface radius, and the maximum crater radius were recorded. The crater elevation data for each shot are presented in appendix IV.

#### a. C-4 Charges

Table II summarizes the data obtained from all shots with the 5-, 15-, and 25-1b charges beneath the 8- and 11-in.-thick concrete. These data




Figure 19. True Soil and Concrete Crater Volumes versus Depth-of-Burst for 25-1b Charge (Fort Sumner)




Figure 20. Crater Radii versus Depth-of-Burst for 25-1b Charge (Fort Summer)



Before Excavation

68-Inch Depth-of-Burst

Figure 21. Crater from Detonation of 25-1b Charge (Fort Summer)


were compiled using the average values of the crater damage dimensions for several shots at the same depth-of-burst.

# (1) 5-1b Charge

## (a) 8-Inch-Thick Concrete

Figures 22 and 23 show crater volumes and crater radii versus depth-of-burst, respectively. The maximum damage depth-of-burst was 30 in. for all parameters except the concrete repair volume for which it was 50 in. for type III craters. (See table II.) Craters caused by the detonation of a 5-1b charge on 11-in.-thick concrete are shown in figure 24.

Varying the depth-of-burst varied all damage quantities (table II). When the depth-of-burst was so selected as to maximize damage to the concrete, the damaged area increased slightly. The combined concrete repair and true soil crater volumes varied from 208 to 276 ft<sup>3</sup> (an increase of



Pigure 22. True Soil and Concrete Crater Volumes versus Depth-of-Burst for 5-1b Charge Under 8-Inch-Thick Concrete (Hays)




Figure 23. Crater Radii versus Depth-of-Burst for 5 lb Charge Under 8 Inch-Thick Concrete (Hays)

Table II


SUNNIARY OF AVERAGE DANIAGE QUANTITIES FOR C-4 CHARGES (HAYS)

		R <sup>2</sup> ),			••							_		_				_							_			~	
		τ(R <sup>2</sup> - <sup>2</sup> fτ²		257	22	214	5.5	223	284	193	Ξ.	77	195	5	192	185	205	340	295	000	179	184	201	250	200	180	244	529 495	
		U/R		0.91	1.23	0.93	1.18	1.65	7.46 21.56	0.89	1.04	1.40	1.28	0.93	1.10	1.20	1.27	12.31	15.70	1.14	1.15	1.46	15.60	L/A	17.48	1.11	1.55	28.05 52.69	
<u>`</u>	ft	~	m						$\frac{2.31}{2.00}$		4.33		4.1.	2.00	5.38	5.61	6.70	3.00	5.00 9.99	10	5.18	5.23	2.76	5.15	2.71	6.87	6.92	5.22	
!! !!	Radius, f	۳,	7	9.41	9.08	9.5 5.5	9.0	9.27	9.55		8.92			9.03	10.58	9.20	10.50	10.43	9.71	8.0.1	9.16	9.19	9.81	90.0	9.12			12.56	
	R	α.	•						0.85		4.33	•	•	5.00	5.38	5.61	ر. د.	.0.0	0.67	4.01	5.18	5.25	0.58	0.67	0.67			0.30 0.30	
	our.I.	Crater Depth (D),	£	5.29	-, -	25	5.39	6.34	6.34 7.33	5.84	4.50	5.00	5.33	4.64	5.94	92.9	8.50	8.25	10.52	4.58	5.84	7.42	9.02	10.05	11.71	2.60	9.19	10.94	1
		te and Soil	кералг	214	.0s	266	254	248	239 208	284	301	282	301		103	314	415	27.	30S 290	513	5.3	414	581	368	556	187	.50	509 465	
	ſt³	Concrete an True Soil	<b>Crater</b>	26	23	92. 12.	1.39	66	30 30	601	125	<u></u> δ.	125	120	0;;;	217	2.78	119	ુ <sup>ફ</sup> ેં.	150	215	281	105	152	1117	361	283	114	
	Volume, f	True	rater	85	દુ જુ	5 %	82	89	48 50	55	[ ]	S		ť	108	<u>c.</u>		118	93	8.5	135	202	104	131	116	262		126	
	27	rete	Repair	186	1,5 185	181	171	180	191 178	229	229	٥ <u>:</u> ز	220	1_1	235	06.	55	27.8	195	250	27:	17	ر د	536	259	225		356 356	,
		Concrete	rater	28	; <del>;</del>	S.	-;	[Z]	0.24	54	<u>ا</u>	i.c.	20	55	61	တ္တ :	ੜ. ੋ	56.5	0.95	÷	{	6.	1.01	?; ?;	1.29	<b>8</b> : 1	= ;	0.55	-
	Depth-of-	Burst, in.		01	30	) (S.	2	os.	£1.50	ន	ا جُ		2	10	30	์ ลี้	= ;	ှာ <del>(</del>	3 2	er 	30	J.	္	င်. ု	110	20	7.8	11.0	F
	Concrete Thickness, in.					s		<del>****</del>		Monte erdag	,					(	y:						-				00		The second secon
		Size, 1b					,	n											,	ų.							<b>1</b>		1

The concrete volume of one slab was 16 ft<sup>3</sup> for the 8-in.-thick slab and 229 ft<sup>2</sup> for the 11-in.-thick slab.



30-Inch Pepth-of-Burst



Shot 53

Craters from Detonation of 5-1b Charge Under 8-Inch-Thick Concrete (Hays) Figure 24.

about 28 percent) within the depth-of-burst range. The average concrete repair volume was about 77 percent of the average combined repair volume.

### (b) 11-Inch-Thick Concrete

Figures 25 and 26 show crater volumes and crater radii versus depth-of-burst, respectively. The maximum damage depth-of-burst for the concrete crater volume and crater radii  $R_1$  and  $R_2$  was 30 in. Although the concrete crater volume for all depths-of-burst was less than the concrete volume of one pad, damage to the concrete was such that one entire pad would have to be replaced (repaired). The combined concrete repair and true soil crater volume varied from 282 to 301 ft<sup>3</sup> (an increase of about 7 percent) within the depth-of-burst range. The average concrete repair volume was about the same as that for the 8-in.-thick concrete (about 82 percent of the combined volume).

### (2) 15-1b Charge

### (a) 8-Inch-Thick Concrete

Figures 27 and 28 show crater volumes and crater radii versus depth-of-burst, respectively. It can be noted from these figures that two peaks occurred-one at a 30-in. and the other at a 70-in. depth-of-burst. The maximum damage depth of-burst for the concrete repair volume and true soil crater volume was 30 in.; it was 70 in. for all other crater damage. Both type III and type III craters occurred at the 70-in. depth-of-burst, but the maximum damage depth-of-burst noted was for type III craters. Craters caused by the detonation of a 15-1b charge on 8-in.-thick concrete are shown in figure 29.

Table II shows that about one and one-quarter pads were damaged with the depth-of-burst having little influence. When the depth-of-burst was so selected as to maximize damage to the concrete, about one and one-half pads were affected. The combined concrete repair and true soil crater volume varied from 247 to 415 ft<sup>3</sup> (an increase of about 68 percent) within the depth-of-burst range. The average concrete repair volume was about 63 percent of the average combined repair volume.

#### (b) 11-Inch-Thick Concrete

Figures 30 and 31 show crater volumes and crater radii versus depth-of-burst, respectively. The maximum damage depth-of-burst for all




Figure 25. True Soil and Concrete Crater Volumes versus Depth-of-Burst for 5-1b Charge Under 11-Inch-Thick Concrete (Hays)




Figure 26. Crater Radii versus Depth-of-Burst for 5-1b Charge Under 11 Inch-Thick Concrete (Hays)




Figure 27. True Soil and Concrete Crater Volumes versus Depth-of-Burst for 15-1b Charge Under 8-Inch-Thick Concrete (Hays)






Figure 28. Crater Radii versus Depth-of-Burst for 15-1b Charge Under 8-Inch-Thick Concrete (Hays)






10-Inch Depth-of-Burst Shot 1

Figure 29. Craters from Detonation of 15-1b Charge Under 8-Inch-Thick Concrete (Hays)



Before Excavation




After Excavation

Shot 5


30-Inch Depth-of-Burst

Figure 29---Continued



Before Excavation

50-Inch Depth-of-Burst



Before Excavation

Shot 11

Figure 29---Concluded




Figure 30. True Soil and Concrete Crater Volumes versus Depth-of-Burst for 15-1b Charge Under 11-Inch-Thick Concrete (Hays)




Figure 31. Crater Radii versus Depth-of-Burst for 15-1b Charge Under 11-Inch-Thick Concrete (Hays)

damage conditions except the concrete repair volume was 50 in.; it was 70 in. for the concrete repair volume. The maximum true crater radius,  $R_3$ , was observed for shallow depths-of-burst (mainly type I craters); however, a second smaller peak was noticeable at a deeper depth where types II and III craters are formed. Craters caused by the detonation of a 15-1b charge on 11-in.-thick concrete are shown in figure 32.

Table II shows that slightly more than one pad on the average was damaged with the depth-of-burst having little influence. The combined concrete repair and true soil crater volume varied from 313 to 444 ft<sup>3</sup> (an increase of about 42 percent) within the depth-of-burst range. The average concrete repair volume was about 65 percent of the average combined repair volume.


# (3) 25-1b Charge, 8-Inch-Thick Concrete

Figures 33 and 34 show crater volumes and crater radii versus depth-of-burst, respectively. The maximum damage depth-of-burst for all damage conditions except the concrete repair volume was 71 in. (type II crater). The maximum damage depth-of-burst for the concrete repair volume was 95 in. (type III crater). The maximum true crater radius,  $R_3$ , was found at the surface. (See table II.) Craters caused by the detonation of a 25-1b charge on 8-in.-thick concrete are shown in figure 35.

Table II shows that about one and three-fourths pads on the average were damaged with the depth-of-burst having little influence. When the depth-of-burst was so selected as to maximize damage to the concrete, slightly more than two pads were affected. The combined concrete repair and true soil crater volume varied from 463 to 750 ft<sup>3</sup> (an increase of about 62 percent) within the depth-of-burst range. The average concrete repair volume was about 53 percent of the average combined repair volume.

### b. Bombs


After completion of the tests using smaller charges, tests were conducted using the MK-81 (250-1b), the MK-82 (500-1b), and the M-117 (750-1b) bombs. Data taken were similar to those taken in the C-4 charge shots. In addition, the apparent crater depth was measured and the ejecta and the apparent crater volume were recorded. All bomb shots were conducted at the midsection of the pavement where the average concrete thickness was approximately 11 in. Table III summarizes the results of the eighteen bomb shots.



Before Excavation

Shot 3A

70-Inch Depth-of-Burst



Before Excavation

Shot 15

Figure 32. Craters from Detonation of 15-1b Charge Under 11-Inch-Thick Concrete (Hays)






Figure 33. True Soil and Concrete Crater Volumes versus Depth-of-Burst for 25-lb Charge Under 8-Inch-Thick Concrete (Hays)



F gure 34. Crater Radii versus Depth-of-Burst for 25-1b Charge Under 8-Inch-Thick Concrete (Hays)



Before Excavation

71-Inch Depth-of-Burst



Before Excavation

Shot 64

95-Inch Depth-of-Burst



Before Excavation

Shot 68

Figure 35. Craters from Detonation of 25-1b Charge Under 8-Inch-Thick Concrete (Hays)

Table III

SUANIARY OF AVERAGE DANIAGE QUANTITIES FOR BONIBS (HAYS)

		Depth	5.65	5.45	202	0.40	.0.50	6.20	6.10	5.83	5.55	2.58	10.60	9.40	03°8	8.6	25.3	95	0.80	
Apparent Grater	ft³	Approximate Grater		830 719	2	17.5	. ‡ ‡	<u>;</u> ;	1220	1342	1266	735	83	7000	4050	3114	3567	1300	1010	35
Appa	Volume, ft	100	2	113	67,	÷ ;	404	i:	1864	1212	1358	<u>چ</u> :	. 8g	0,77.2	3024	3225	35.5	2540	0077	35
		1	**************************************	221	593	2.5	236	ico	652	22.5	653	1008	224	1275	1516	1495	1500	1357	808	383
	- (D2 - D2)	(		637 605	1094	782	0771	1900	1418	1202 862	1032	1043	2037	1,7	1718	2854	2286	1924	9641	1983
	೭	۵	<u>.</u> ^	13.70	12.99	12:51	14,23		16.60	19.89	*	36.98	< <b>*</b>	*	21.44	* *	* ;	2:	2 %	×*
	Crater Radius,	£	<u>د</u> ~	30.33	77.	19.50	27.68	7: 1	27.00	27.90	.8.8	7.	34.45 24.45	90 01	5	30.05	27.7	7	7 1	.6.1c
	Chate	۵	 -	13.70	12.99	2	22.23	15.34	16.66	19.89	18.44	16.98	87. 87.	1, 2,	7.7.	5.	27.75	ے د زور	2 %	16.08
rater	20402	Depth		15.10	15.60	0	19.30		13.10	9.4	*	35.00	K * K	*	20.00	* ·	*	2.5	3.5	10.01
True Crater		and Soil	Repair	3,63	1,554	5,188	6,208		5,050	8,010	**	\$89	* * * *	*	15,734	*	*	16,572	50,50	**
		Concrete and Soil	Crater	2,998	3,350	2,875	4,583		3.750	6,911	*	٤, ٢	* *	*	14,152	*	*	15,942	11,139	1 * * * * * * * * * * * * * * * * * * *
	Volum, fr³	Seil	Cre.er	2,457	3,064	2,393	4,000		2.950	5,77	: # •	5,50	* *	;	12,8,4	*	*	12,527	503,6	11,005
	Ve	crete	Repair	1180	1490	1095	2208	5035	2100	2242	1953	1788	2021	25.24	2900	3862	3381	4045	5555	2000 3100
		Conc	Crater	£ 25	486	470	583	ç	800	1140	786	831	151	23.52	1325	1243	1284	1415	1537	803
	Pepth-of- kurst, ft				22	12	25	À	o	21.2	10	S	21.8	:	121	15	15	38	80	20.5
	Shot					72	55.	,	\$3	30	80 and 84*	82	8 83	6	:3	25	90 and 92*	55	94	95 and 34"
	Pruh Size, 1b					OFF-831					003.	(58-35)				_	750	(V-117)		

## (1) MK-81 (250-1b Bomb)

Five of the six craters were excavated. Figures 36 and 37 show true crater volumes and crater radii versus depth-of-burst, respectively. Figure 36 shows that the maximum damage depth-of-burst for the concrete crater and the concrete repair volume occurred at a 15-ft depth-of-burst. However, the maximum damage depth-of-burst for the other damage conditions could not be determined since the crater for the shot at the 17-ft depth-of-burst was not excavated. Craters caused by the detonation of an MK-81 bomb are shown in figure 38.

Table III shows that about six and three-fourths pads on the average were damaged by varying the depth-of-burst from 8 to 17 ft. However, the maximum damage to the concrete was about nine and three-fourths pads at a depth-of-burst of 15 ft. The combined concrete repair and true soil crater volume varied from 3,391 to 6,208 ft<sup>3</sup> (an increase of about 83 percent) for the five craters excavated. The average concrete repair volume was about 36 percent of the average combined repair volume.

### (2) MK-82 (500-1b Bomb)

Three of the six craters were excavated. Figures 39 and 40 show true crater volumes and crater radii versus depth-of-burst, respectively. The maximum damage depth-of-burst for the concrete crater volume was 12 ft; it was 18 ft for the concrete repair volume. (This was based on the data obtained by averaging the damage for two shots at a 12-ft depth-of-burst. However, one of these two shots produced greater damage to the concrete than the shot at the 18-ft depth-of-burst.) The apparent crater depth was largest at the 12-ft depth-of-burst. Craters caused by the detonation of an MK-82 bomb are shown in figure 41.

Table III shows that about eight and three-fourths pads on the average were damaged by varying the depth-of-burst from 9 to 21 ft. However, the maximum damage to the concrete was slightly more than nine and three-fourths pads at a depth-of-burst of 12 ft (slightly larger than that for the MK-81 bomb). The combined concrete repair and true soil crater volume varied from 5,050 to  $8,010~\rm{ft}^3$  (an increase of 59 percent) for the three craters excavated. The average concrete repair volume was about 29.5 percent of the average combined repair volume for the three shots excavated.




Figure 36. True Soil and Concrete Crater Volumes versus Depth-of-Burst for MK-81 Bomb (Hays)




Figure 37. Crater Radii versus Depth-of-Burst for MK-81 Bomb (Hays)



After Excavation
Shot 71 8-Foot Depth-of-Burst



Before Excavation



After Excavation
Shot 70 10-Foot Depth-of-Burst

Figure 38. Craters from Detonation of MK-81 Bomb (Hays)



Before Excavation



After Excavation

Figure 38---Continued



Before Excavation



After Excavation

Shot 73

15-Foot Depth-of-Burst

Figure 38---Concluded




Figure 39. True Soil and Concrete Crater Volumes versus Depth-of-Burst for MK-82 Bomb (Hays)





Figure 40. Crater Radii versus Depth-of-Burst for MK-82 Bomb (Hays)



Before Excavation

9-Foot Depth-of-Burst



Before Excavation

Shot 80

Figure 41. Craters from Detonation of MK-82 Bomb (Hays)




Before Excavation



After Excavation

Figure 41---Continued



Crater Not Excavated

18-Foot Depth-of-Burst



Crater Not Excavated

Shot 83

Figure 41---Concluded

# (3) M-117 (750-1b Bomb)

Three of the six craters were excavated. Figures 42 and 43 show true crater volumes and crater radii versus depth-of-burst, respectively. The maximum damage depth-of-burst for the concrete repair volume was 18 ft. Craters caused by the detonation of an M-117 bomb are shown in figure 44.

Table III shows that about fourteen pads on the average were damaged by varying the depth-of-burst from 12 to 20.5 ft. However, the maximum damage to the concrete was nearly eighteen pads at a depth-of-burst of 18 ft. The combined concrete repair and true soil crater volume for the three shots varied from 12,936 to 16,572 ft<sup>3</sup> (an increase of 28 percent). The average concrete repair volume was about 22.7 percent of the average combined repair volume for the three shots excavated.




Figure 42. True Soil and Concrete Crater Volumes versus Depth-of-Burst for M-117 Bomb (Hays)






Figure 43. Crater Radii versus Depth-of-Burst for M-117 Bomb (Hays)



Crater Not Excavated


12-Foot Depth-of-Burst



Before Excavation

Shot 90

Figure 44. Craters from Detonation of M-117 Bomb (Hays)



Shot 93

Before Excavation 18-Foot Depth-of-Burst



Crater Not Excavated

Shot 95

20.5-Foot Depth-of-Burst

Figure 44---Concluded

#### SECTION VII

#### DATA ANALYSIS

In the previous section, the crater data obtained from each of the charges and bombs at the Fort Summer and Hays test sites were presented. In this section, an attempt is made to analyze some of the pertinent crater damage data as a function of charge size and depth-of-burst.

#### 1. FORT SUMNER DATA

Table IV shows crater damage for the shallowest depth-of-burst and the maximum damage depth-of-burst. Figure 45, which shows crater damage for the three C-4 charge sizes, reveals the following:

- (1) The damage increases with increasing charge size at the shallowest depth-of-burst.
- (2) At the maximum damage depth-of-burst, the damage caused by the 15-1b charge is higher than expected since it is about the same as that caused by the 25-1b charge. It may be noted from table IV that the shallowest depth-of-burst as well as the maximum damage depth-of-burst varies for each charge size.

Table IV

SHALLOWEST AND MAXIMUM DAMAGE DEPTH-OF-BURST DATA FOR C-4 CHARGES (FORT SUMNER)

Charge	Depth-of-		Surface Crater							
Size, lb	Burst, in.	Conc	rete	True	Concrete	and Soil				
		Crater	Repair	Soil Crater	Crater	Repair	1,1,1			
5	17 33	12 28	117 117	20 42	32 70	137 159	2.56 3.90			
	10 50	28	130 251	67	95	197	3.90			
15	70	88	251	291	379	479	6.85			
25	34 68	73 83	212 254	124 217	197 300	356 470	6.27 6.70			




Figure 45. Crater Damage versus Charge Size (Fort Sumner)




Figure 46 shows the ratio of average concrete repair volume to the average combined repair volume as a function of the C-4 charge size. This figure indicates that the concrete repair volume decreases as the charge size is increased; however, the concrete repair volume is more than 50 percent of the combined repair volume. Figure 47 shows the area of concrete to be removed (because of heaves and cracks) versus depth-of-burst for all the craters and all the C-4 charge sizes. In general, the area of concrete to be removed increases with increasing depth. However, for the 5-1b charge, this increase is very small; for the 15-1b charge, the concrete area to be removed increases up to a depth-of-burst of 90 in. and then decreases. Figure 48 shows the true crater depth versus depth-of-burst for all charges. These data were fitted with the straight line y = A + Bx. It might be expected that, for a given depth-of-burst, the larger the charge the greater the true crater depth. This trend is seen in figure 48.

Based on the data given in table I, the following limits of aspect ratios (D/R) can be specified for the three types of craters:

Crater Type	D/R <sub>1</sub>
I	≤1.0
II	$>1.0$ to $\le 5.0$
III	>5.0

Figure 49 shows the aspect ratios for different depths-of-burst for the three crater types. The data in this figure were taken from appendix III. Although one would expect type I craters to occur at shallow depths-of-burst and type II craters at intermediate depths-of-burst, it is seen that both crater types occurred in these depth-of-burst ranges (fig. 49). However, type III craters occurred only at the deeper depths-of-burst.

## 2. HAYS DATA

## a. C-4 Charges

The thickness of the concrete slab at Fort Summer was uniform throughout, but at Hays there were concrete slabs of two thicknesses (8 and 11 in.). This should help evaluate the effect of the concrete thickness on the crater damage. However, it appears from table II that, although the thickness does




Figure 46. Ratio of Average Concrete Repair Volume to Average Combined Repair Volume versus C-4 Charge Size (Fort Sumner)

have some influence on the crater damage, the differences in concrete repair volumes, etc., are not very significant. For the 5-lb charge at 20-, 30-, and 40-in. depths-of-burst (with the maximum damage depth-of-burst assumed to be 30 in.), the average concrete area to be repaired in the 8-in.-thick concrete was about 9 percent larger than that in the 11-in.-thick concrete. For the 15-lb charge at 30-, 50-, and 70-in. depths-of-burst (with the maximum damage depths-of-burst assumed to be 30 in. for the 8-in.-thick concrete area and 70 in. for the 11-in.-thick concrete area), the average concrete area to be repaired in the 8-in.-thick concrete was about 17.5 percent larger than that in the 11-in.-thick concrete.




Figure 47. Area of Concrete to be Removed versus Depth-of-Burst for  $\Omega$ -4 Charges (Fort Sumner)




Figure 48. True Crater Depth versus Depth-of-Burst (Fort Summer)




Figure 49. Aspect Ratio versus Depth-of-Burst for C-4 Charges (Fort Summer)

Table V shows the crater damage for the shallowest depth-of-burst and the maximum damage depth-of-burst. Figure 50 shows crater damage for the three C-4 charge sizes and the two concrete thicknesses. For the 8-in.-thick concrete, the damage in general increased with increasing charge sizes for both the shallowest depth-of-burst and the maximum damage depth-of-burst. No tests were conducted with the 25-lb charge under the 11-in.-thick concrete.

Figure 51 shows the ratio of average concrete repair volume to the average combined repair volume as a function of the C-4 charge size. This figure indicates that the concrete repair volume decreases as the charge size is increased; however, the concrete repair volume is still slightly more than 50 percent of the combined repair volume for the three C-4 charges tested.

Table V .

SHALLOWEST AND MAXIMUM DANAGE DEPTH-OF-BURST DATA FOR C-4 CHARGES (HAYS)

Size, Thickn		Depth-of- kurst, in.							
	Concrete Thickness, in.		Conc	rete	True Soil	Concre So	Surface Crater Radius (R <sub>1</sub> ), ft		
			Crater	Repair	Crater	Crater	Repair	1/, "	
5	8	10 30 50	28 59	186 191	28 82	56 136	214 266	3.62 5.1	
,	11 20		54 54	229 229	55 72	109 125	284 301	4.33 4.33	
15	8	10 30 70	53 94	171 235	76 184	129 278	247 415	5.00 6.70	
	11	10 50 70	-∔6 79	230 276	83 202	130 281	313 444	4.01 5.23	
25	8	50 71 95	99 101	225 355	262 486	361 587	487 750	6.87 6.92	





Figure 50. Crater Damage versus Charge Size (Hays)






Figure 51. Ratio of Average Concrete Repair Volume to Average Combined Repair Volume versus C-4 Charge Size (Hays)

Figure 52 shows the area of concrete to be removed versus depth-of-burst for the three C-4 charge sizes. For the 5- and 15-lb charges, the area of concrete to be removed increased by 25 to 50 percent with increasing depths of-burst; however, for the 25-lb charge, ti. damaged area increased by 150 percent (i.e., from about 200 ft<sup>3</sup> at 50 in. to about 500 ft<sup>3</sup> at 119 in. over the range of depth-of-burst tested). An examination of the data in table II reveals a general trend indicating that the concrete area to be removed is a major part of the total concrete repair area. For instance, the concrete area to be removed is about 80 percent of the total concrete area to be repaired for the 5-lb charge.




Figure 52. Area of Concrete to be Removed versus Depth-of-Burst for C-4 Charges (Hays)

The limits of aspect ratios observed at Fort Sumner were similar to those calculated from the data at Hays (fig. 53). These data were taken from appendix IV.

The data pertaining to the C-4 charges were assumed to be quite reliable since several tests were performed with each charge at the same depth-of-burst. Therefore, an attempt was made to analyze these data by similitude relationships to verify the scaling factor and the distortion factor.

Similitude analysis of the crater phenomenon gives the following relationship based on mass scaling by neglecting gravity (ref. 3):

$$(W_1/W_2)^{1/n} = (C_1/C_2)$$
 (1)

where

n = scaling factor

W = weight of explosive in prototype and model, respectively  $C_{1,2}$  = linear parameters in prototype and model, respectively.

Table VI shows the scaling factors obtained by scaling the maximum damage depth-of-burst and the true surface crater radius, R<sub>1</sub>. The values of n varied from 1.40 to 2.50 for the maximum damage depth-of-burst and from 1.82 to 5.50 for R<sub>1</sub>, excluding the data from the 15-1b charge under the 8-in.-thick concrete. For the 15-1b charge under the 8-in.-thick concrete, either a low value of n (i.e., 0.44) or very large values of n (viz., 34.07 and 15.82) were obtained. A constant scaling factor could not be obtained from the given relationship because the pavement system was not geometrically scaled for different charges.

Furthermore, similitude analysis gives the relationship between the weights of the charges,  $W_1$  and  $W_2$ , and the crater volumes,  $V_1$  and  $V_2$ .

$$(W_1/W_2) = (V_1/V_2)$$
 (2)

If this relationship is not satisfied exactly for distorted models, a distortion factor, m, may be determined to give the following identity:

$$(W_1/W_2) = m(V_1/V_2)$$
 (3)

Table VI shows the computed distortion factors for all maximum crater volumes. For the concrete repair volume, it varied from 1.10 to 2.69; for the true soil




Figure 53. Aspect Ratio versus Depth-of-Burst for C-4 Charges (Hays)





Figure 53---Continued



(e) 25-lb Charge, 8-Inch-Thick Concrete

Figure 53---Concluded

SCALING AND DISTORTION FACTORS FOR C-4 CHARGES (HAYS) Table VI

	<del></del>			_			
nd True r Crater	**	1.77	,	2.01	0.92	0.99	1.00
Concrete and Concrete and Twe True Soil Crater Soil Repair Crater	Volume,	266		301	415	444	750
e and Crater	*	1.16		1.06	0.79	08.0	1.00
Concrete and True Soil Crater	Volume, ft³	136		125	278	281	587
le rater	#*	0.84		0.74	0.65	69.0	1.00
True Soil Crater	Volume, ft³	82		72	184	202	486
Repair	**!4		5:69	5.23	1.10	1.30	1.00
Concrete	Concrete Repair Volume, p**		191	525	235	276	355
rete ter	#*#	2.92		2.67	1.55	1.30	1.00
Concrete Crater	Volume, ft³	89		54	Þ6	7.9	101
Crater Radius	n*	5.50		5.42	6.70 15.82	1.82	1.00
Crater	R, ft	5.17		4.53	6.70	5.23	6.92
laximum Damage Depth-of-Burst	n*		2.50 (2)	1.40 (1)	0.44 (2) 34.07 (1)	1.46 (1) 1.67 (2)	1.00 (1)
Maximum Damage Depth-of-Burst	Depth, ft	2.50	4.17	2.50	2.50	4.17	5.92 7.92
Concrete	in.	8		11	80	11	8
Charge	Charge Size, 1b				<u>r</u>		25

\*Scaling factor (n) =  $\log(W_1/W_2)/\log(C_1/C_2)$ , where  $W_1$  = 25-1b charge,  $W_2$  = 5-1b or 15-1b charge, and  $C_{1,2}$  = maximum damage depth-of-burst or R.

\*\*Bistortion factor (m) =  $(W_1/W_2)/(W_1/W_2)$ , where  $W_1$  = 25-1b charge,  $W_2$  = 5-1b or 15-1b charge, and  $W_{1,2}$  = concrete or soil volumes.

†(1) Using maximum, damage depth-of-burst for 25-1b charge = 5.92 ft.

(2) Using maximum damage depth-of-burst for 25-1b charge = 7.92 ft.

crater volume, it varied from 0.63 to 0.84. A larger distortion, which increases as the ratio of the explosive weights increases, is apparent when the concrete volumes are compared. Again, this distortion is expected since the pavement system was not scaled. For the combined crater volume, the distortion factor approaches unity mainly because the concrete crater volumes for the smaller charges are larger than the predicted values, while the true soil crater volumes are less than the predicted values.

## b. Bombs

Table VII shows the crater damage for the shallowest depth-of-burst and the maximum damage depth-of-burst. Figure 54 shows the crater damage for the bombs. It is seen from this figure that, in general, the damage increases with increasing bomb sizes both for the shallowest depth-of-burst and the maximum damage depth-of-burst.

Table VII

SHALLOWEST AND MAXIMUM DAMAGE DEPTH-OF-BURST DATA
FOR BOMBS (HAYS)

Bomb	Depth-of-		Surface				
Size,	Burst,	Conc	rete	True Soil	Concrete	Crater Radius	
10		Crater	Repair	Crater	Crater	Repair	(R <sub>1</sub> ), ft
250 (MK-81)	8 15	541 583	1180 2208	2,457 4,000	2,998 4,583	3,637 6,208	13.70 14.23
500 (MK-82)	9 12 15 18	800 98c	2100 2177	2,950 5,897	3,750 6,911	5,050 3,010	16.66 18.44
750 (M-117)	12 15 18	2137	2534 3690	12,834	14,152	15,734	27.24




Figure 54. Crater Damage versus Bomb Size (Hays)




Figure 55 shows the area of damaged concrete to be removed versus depth-of-burst for the three bomb sizes. There appears to be no consistent trend for the different bombs with increasing depth-of-burst. A comparison of the volume of concrete to be removed and the concrete repair volume for the bombs (table III) indicates the general trend that the concrete area to be removed is a major part of the total concrete repair area. For the three bomb sizes tested, the concrete area to be removed was about 60 percent of the total concrete repair area.

Figures 56 and 57 show the apparent crater depth, and the ejecta versus depth-of-burst, respectively, for the three bomb sizes. Figure 56 indicates that the apparent crater depth generally decreases with increasing depths-of-burst. This indicates that a camouflet will occur with greater depths-of-burst. Figure 57 shows that, for the MK-82 and the M-117 bombs, the ejecta volume increases with increasing depths-of-burst up to a 15-ft depth-of-burst and then it decreases with greater depths-of-burst. This trend was not found for the MK-81 bomb. The apparent crater volume versus depth-of-burst for the three bomb sizes is plotted in figure 58. Here again, the occurrence of a camouflet at deeper depths-of-burst is indicated by the fact that the apparent crater volume approaches zero with deeper depths-ofburst for each of the bombs tested. In figure 58, the volumes were computed by two different methods--the cone formula which assumes that the apparent crater can be approximated by a cone, and a more accurate method based on actual elevation measurements. As this figure indicates, the apparent crater volumes can be computed very well using the cone formula.

Table VIII summarizes the apparent crater data for the bombs tested. As the table shows, the volume of available material on the surface (i.e., ejecta and concrete repair volume less concrete crater volume) is, in general, much larger than the apparent crater volume and, hence, can possibly be used as backfill for repair purposes. Appendix II lists the in-place densities taken on the ejecta, the fallback material, and the crater wall. These densities were either determined by sand cone tests or by balloon density tests. As these data indicate, the ejecta and the fallback material are less dense than the material in the crater wall.





Figure 55. Area of Concrete to be Removed versus Depth-of-Burst for Bombs (Hays)



The second secon

Figure 56. Apparent Crater Depth versus Depth-of-Burst for Bombs (Hays)




Figure 57. Ejecta versus Depth-of-Burst for Bombs (Hays)




Figure 58. Apparent Crater Volume versus Depth-of-Burst for Bombs (Hays)

Table VIII
SUMMARY OF APPARENT CRATER DAMAGE FOR BOMBS (HAYS)

Bomb	Depth-of-	Concre	te Volume	, ft³	Ejecta Volume,	Material Available,	Apparent Crater	
Size, 1b	ft   Crater   Repair   (2)		(2)-(1) (3)	ft <sup>3</sup> (4)	ft <sup>3</sup> (3)+(4)	Volume, ft³		
250 (MK-81)	8 <sub>*</sub> 10 13 15 17	541 554 470 583 439	1180 1383 1095 2208 2095	639 779 625 1625 1656	221 420 274 216 639	860 1199 899 1841 2295	693 746 42 None None	
500 (MK-82)	9* 12* 15 18 21	800 986 831 486 151	2100 1933 1788 2177 2021	1300 947 957 1691 1870	652 653 1008 407 554	1952 1600 1965 2098 2424	1864 1398 681 33 108	
750	12 <sub>*</sub> 15	2137 1283	2534 3381	397 2098	1275 1506	1672 3604	4370 3575	
(M-117)	18 <sup>*</sup> 20.5	1476 802	3690 2700	2214 1898	1083 383	3297 2281	1900 35	

<sup>\*</sup>Average of two shots.

# c. C-4 Charges and Bombs

Figure 59 shows true crater depth versus depth-of-burst for all C-4 charges and bombs. These data, which seem to fall within a narrow band, were approximated by the linear equation  $y = n^{-1}$  Bx as shown in the figure.




Figure 59. True Crater Depth versus Depth-of-Burst for C-4 Charges and Bombs (Hays)

## SECTION VIII

### SMALL-SCALE MODEL FEASIBILITY STUDY

The objectives of this feasibility study were to review pertinent available literature and to conduct small-scale field tests to determine if pavement systems and cratering charges can be modeled using similitude relationships derived for cratering problems in earth media; however, the field tests conducted at Fort Summer and Hays were not modeled. The full-scale pavement tests conducted at CERF were modeled in this feasibility study.

#### 1. LITERATURE SURVEY

A limited literature survey was conducted to review the progress made in the field of cratering in genera and to study past accomplishments in the area of pavement cratering.

Johnson and Fischer (ref. 4) reported on a laboratory study of the effects of mechanical properties of material on crater dimensions which was conducted by the Bureau of Mines. They found that the static tensile strength was related to the maximum scaled crater dimensions obtained by blasting. However, the nature of this relationship was such that it was useless for cratering predictions. Field data were found to be consistent with laboratory tests for both synthetic material and rock. More scatter occurred between other physical properties and maximum crater dimensions; however, some trend relationships existed. They concluded that the maximum charge depth at which cratering would occur was not determined by the strength of the material but by the pulse attenuation in the material, and that the maximum crater depths tended to be more or less constant between scaled charge depths of 0.5 and 2.

Vesić (ref. 2) has given an extensive review of the work accomplished up to 1963 on theoretical studies of the mechanics of explosive cratering in an earth medium. Depending on the relative depth of the explosive charge, three different crater types were identified: (1) camouflet and subsidence crater; (2) deep crater; and (3) shallow or surface crater. A camouflet (the type III crater described in this report is similar to a camouflet) is formed by expansion of the gas sphere. If the cavity roof collapses, a subsidence crater appears at the ground surface. A deep crater (similar to the type II craters in this report) is formed by expansion and breakthrough of the gas sphere,

followed by slope failures. The reflected tension waves may be significant during the formation of this type of crater in some media. Shallow or surface craters are formed by different mechanisms. Depending on the characteristics of the medium, plastic deformation or fracturing by the stress or shock waves is of the greatest importance. Vesić presented a theory which enabled rational analysis of camouflets and subsidence craters and deep craters that are of primary interest to the engineer. The consequences of the proposed theory were examined by Vesić and found to be in general agreement with experience. Considering the strength and deformation properties of the medium, he derived a modified scaling law for crater dimensions and found that the conventional scaling exponent was not a constant, but varied with the properties of the earth media and the actual depth-of-burst.

Moraski and Teal (ref. 5) reported on an investigation of the effects of gravity on explosive crater formation in a cohesionless medium. They concluded that crater diameters and depths varied inversely with gravity. It is very interesting to note that they conducted tests at 1.0 g in the laboratory and at 0.17, 0.38, and 2.5 g on a C-131B aircraft.

Chabai (ref. 3) conducted a similitude study on the scaling dimensions of craters produced by buried explosives. Using the principles of dimensional analysis, he determined that linear crater dimensions were proportional to the cube root of the charge weight, whether the explosion was represented in energy or mass dimensions, when gravitational effects were neglected. When gravity was included in the dimensional analysis, the cube-root scaling was valid when a mass dimension was used for the explosive charge; however, when the charge was expressed in energy dimensions, crater dimensions were proportional to the fourth root of the charge weight. Divoky (ref. 6) in his discussion of Chabai's paper indicated that if similarity was achieved between two experiments, both the mass gravity scaling law and the energy scaling law, each correctly derived, should be consistent. He concluded that mass requires the scaling of the energy release per unit mass of explosive and this, in turn, should reduce the mass law to the corresponding energy law.

Saxe and DelManzo (ref. 7) conducted research on scaling conventional high explosive and nuclear craters. They found that the linear relationships of the dimensionless parameters developed by them were useful for crater predictions. Furthermore, these relationships provided a capability of scaling from high

explosive to nuclear events not only for a particular radius or depth, but for shape as well, i.e., maintenance of a specific radius-to-depth ratio.

Galbraith (ref. 8) conducted an experimental study on motion analysis of small explosive cratering events in dry Ottawa sand by use of the cube-root scaling of the explosive charge. The scaling of time was unsuccessful.

Bessert (ref. 9), in his experimental study on the effects of charge size and depth-of-burst variations in laboratory-scale cratering experiments in sand, found that the empirically derived scaling exponent of 1/3.4 provides a better scaling relationship for crater dimensions than either the cube-root or fourth-root scaling rules. Furthermore, this scaling provided a better correlation with high-energy explosion data than either the cube-root or fourth-root scaling. Bessert recommended computer techniques to determine exact scaling exponents and analysis of volume variation to determine scaling relationship.

Carlson and Newell (ref. 10) reported on an experimental study to verify the relationship between soil crater ejecta distribution and its origin for single high-explosive charges of various weights detonated at various depths-of-burst. Using cube-root scaling Carlson and Newell concluded that crater radius, depth, and volume are proportional to charge weight.

D'Andrea, et al., (ref. 11) reported on experiments in a homogeneous granite to test scaling laws for various charge weights. They found that agreement among the data was best when empirical scaling exponents greater than one-third were assumed.

No definite conclusions can be drawn about the scaling exponent to be used for modeling cratering problems from the foregoing brief review of the literature. Furthermore, it seems that no model tests of pavement cratering have been conducted so far.

## 2. PRELIMINARY MODEL STUDY

## a. Pavement System Modeling

This study consisted of modeling the rigid pavement system (reported in ref. 1) which was tested in the field using C-4 explosives. Figure 60 shows this rigid pavement system. One-half of the section consisted of a 14-in.-thick Portland cement concrete slab on a 6-in.-thick gravel base course; the other half consisted of an 8-in.-thick Portland cement concrete slab on a




Figure 60. Full-Scale Rigid Pavement System [after Pichumani (ref. 1)]

12-in.-thick gravel base course. The entire section rested on a 6-ft-thick clay subgrade.

The scaling relationships mentioned in the literature survey seem to have been established for explosives in more or less homogeneous media. However, the objective of the present research was to model the cratering events on airfield pavement systems which consist of several layers of different materials. Therefore, preliminary dimensional analysis was performed on a cratering event in a pavement section consisting of two layers. From this analysis it was observed that the cube-root scaling was valid even for the layered pavement system when gravity was neglected. Consequently, it was decided to model the rigid pavement system (fig. 60) using the cube-root law for scaling.

The original rigid pavement system was 100 by 50 ft. This pavement was divided by joints into eight 25- by 25-ft panels. The positions of two shots fired in the original pavement are shown in figure 60a. Figure 61a shows the test section which was built to model the 25- by 25-ft panel located at the northeast corner of the original pavement shown in figure 60a. This panel was chosen to keep the model pavement as small as possible and also because the shot in this panel did not affect the adjacent panels of the 50- by 50-ft section of the prototype. Figure 61b shows the model of the 50- by 50-ft test section which consisted of four panels. The first eight tests were conducted on the model pavement section shown in figure 61a; the last two tests, 9 and 10, were conducted on two of the panels of the model test section shown in figure 61b. The K-4 panel was used for test 9 and the K-2 panel for test 10.

By using cube-root scaling and neglecting gravity effects, the following relationship between linear dimensions and quantity of explosive charge was obtained for craters produced by buried explosives (ref. 3):

$$\frac{C}{C_2} = \left(\frac{\rho_1}{\rho_2}\right)^{1/3} \left(\frac{W}{W_2}\right)^{1/3} \tag{4}$$


where


C = linear dimension

 $\rho$  = density of medium

W = weight of charge


1, 2 = prototype and model, respectively.





(a) Test Section for Tests 1 Through 8

Figure 61. Models of Pagid Pavement System



(b) Test Section for Tests 9 and 10
Figure 61---Concluded

If the densities of the materials used for the model and the prototype are the same, i.e.,  $\rho_1$  =  $\rho_2$ , eq. (4) becomes

$$\left(\frac{C_1}{C_2}\right) = \left(\frac{W_1}{W_2}\right)^{1/3}$$
(5)

In the original pavement system,  $C_1$  was 25 ft for tests 1 through 8 and 50 ft for tests 9 and 10; and  $W_1$  was 1.5 lb (C-4 explosive). A model charge of 5 gm of C-4 explosive was used to obtain the linear dimensions of the model test sections,  $C_2$ , shown in figure 61.

#### b. Construction of Model Test Sections

Processed clay was used as the subgrade material overlying the existing silty sand. The base course consisted of 1-1/4-in.-thick compacted gravel underlying a 2-3/4-in.-thick Portland cement concrete slab. Keyed longitudinal joints were constructed along the centerline of the pavement for tests 9 and 10. In addition, grooved transverse joints were provided. Oiled dowel bars, 1/8 in. in diameter and 6 in. long, were placed on 3-in. centers across these transverse sections during the concreting operation.

The 1.5-lb C-4 explosive charge which simulated the air-dropped cratering weapon in the prototype tests was modeled by electrically detonating the scaled quantity of uncased explosives at the bottom of a 6-in.-deep hole in the center of the pavement slab.

#### c. Results

Physical measurements of the pertinent variables such as the concrete crater and concrete repair volumes, the true soil crater volume, the surface diameter, and the maximum crater diameter were made to evaluate the effect of small cratering charges on pavements. Each shot was also photographically recorded. The crater volume was calculated from the approximate linear measurements of the crater shape. In addition, the in-place soil density,  $\gamma$ , and the moisture content, w, at the bottom of the crater were determined by taking tube samples after the crater was excavated. The compressive strength of the concrete cylinders,  $f_c$ , was determined by testing on the day of detonation. These laboratory test data are given in table IX.

Table IX

MODEL STUDY TEST DATA

			Soi1	Concrete				
Test	Test Charge Weight, Density gm (γ), pcf		Moisture Content (w),	Compressive Strength (f'), psi	Curing Time, days			
1	5.0	111.5	9.8	4050	17			
2 * 3	11.3	111.2	7.8	4023	8			
3	9.0	112.8	11.6	3395	8			
4	11.5	112.8	11.6	3395	8			
5 **	13.0	112.8	11.6	3395	8			
6 **	7.0	112.8	11.6	3550	8			
7	17.5	112.8	11.6	3550	8			
8	15.0	112.8	11.6	3550	8			
9 <sup>†</sup>	17.5	112.0	10.4	3373	9			
10 <sup>††</sup>	17.5	108.3	12.2	4772	28			

<sup>\*\*</sup>Models for tests 3, 4, and 5 were prepared on the same day.

\*\*Models for tests 6, 7, and 8 were prepared on the same day.

\*\*Test 9 was conducted on the northwest panel of the slab.

Test 10 was conducted on the southwest panel of the slab after the northwest panel was repaired.

The craters caused by the different quantities of explosive charges used in the model tests are presented in appendix V. Table X summarizes the true crater damage for these tests. In test 1, a 5-gm charge of C-4 explosive was used. The concrete slab was not damaged. Since the 5-gm shot did not cause any damage, test 2 was conducted using a model test section similar to the one used in test 1 and an explosive charge of 11.3 gm which corresponds to an n value of 2.5 in eq. (1). This shot produced radial cracks, but no

 ${\tt Table}~{\tt X} \\ {\tt SUMMARY}~{\tt OF}~{\tt TRUE}~{\tt CRATER}~{\tt DAMAGE}~{\tt FOR}~{\tt MODFL}~{\tt TESTS} \\$ 

								_			
dius, ft	R.	00.00	0.25	0.25	0.30	0.32	0.23	0.20	0.67	1.00 *	1.25
Crater Radius, ft	۳,	00.0	0.03	0.03	0.03	0.03	0.03	0.20	0.03	1.00 *	1.25
True Crater Depth,	ft	00.0	0.83	0.83	0.79	0.77	0.71	1.18	0.77	1.04 * (0.98)	0.92
and True r Volume,	Repair	00.0	0.07	0.04	0.09	0.10	0.04	5.54	0.13	5.58 * (5.55)	5.51
Concrete and True Soil Crater Volume, ft³	Crater	00.00	0.07	0.04	0.09	0.10	0.04	0.22	0.13	0.95 * (1.10)	1.26
True Soil Crater Volume, ft³	Crater	00.00	0.07	0.04	0.09	07.0	0.04	0.19	0.13	0.23 * (0.20)	0.16
te Volume, ft³	Repair	00.00	0.00	0.00	0.00	0.00	0.00	5.35	00.0	5.35 * (5.35)	5.35
Concrete	Crater	00.0	00.0	00.00	0.00	00.00	00.00	0.03	00.00	0.72 * (0.91)	1.10
Charge Weight,	mg	5.0	11.3	0.6	11.5	13.0	7.0	17.5	15.0	17.5	17.5
Test		Ħ	2	3	4	S	9	7	8	6	10

\* Average of tests 9 and 10.

Note: Depth-of-burst was 0.5 ft for all tests.

crater of the shape and size corresponding to those in the prototype test was formed. Therefore, two sets of three shots with different charges (i.e., tests 3, 4, and 5 with charges of 9.0, 11.5, and 13.0 gm, respectively; tests 6, 7, and 8 with charges of 7.0, 17.5 and 15.0 gm, respectively) were made to see if any of these shots would reproduce the damage parameters noted in the prototype test. These charges corresponded to different n values since C/C in eqs. (1) and (5) was constant by model construction. The 17.5-gm charge, used in test 7 produced damage quite similar to that in the prototype test. Therefore, tests 9 and 10 were conducted using a charge of 17.5 gm to check the reproducibility of these test results. The damage parameters visually observed in tests 9 and 10 were reasonably similar to those observed in tests 1 and 13 of the prototype study (ref. 1). Table XI summarizes the damage parameters pertaining to shots 1 and 13 of the prototype study. The explosive charge used in each prototype shot was 1.5 lb of C-4 explosive. From eq. (1), the scaling factor is given by

$$n = \frac{\log(W_1/W_1)}{\log(C_1/C_2)}$$
 (6)

where

W = weight of C-4 explosives in prototype (681 gm) and model, respectively

C<sub>1,2</sub> = linear parameters such as crater depth, etc., for prototype and model, respectively.

If  $C_1$  and  $C_2$  represent crater volumes, n will equal unity; if not, a distortion factor, m, will be obtained.

Table XII shows the computed scaling factor comparing the prototype data to the average values of damage parameters noted in tests 9 and 10. Although the model was scaled from the prototype by cube-root scaling using  $W_2 = 5$  gm, the same model was used for the larger charges up to 17.5 gm. The value of n in eq. (6) works out to 2.24 for the 17.5-gm charge when comparing crater depths of the prototype and model. However, as seen from table XII, a scaling factor of 3.09 is obtained against the theoretical value of 2.24. Comparison of the crater volumes of the prototype and model shows that the distortion factor, m, is 1.53, 0.67, and 1.28 for the concrete crater volume, the true soil crater volume, and the combined concrete and true soil crater volume, respectively.

Table XI
SUMMARY OF TEST RESULTS FROM REFERENCE 1

Test*	Concrete Volume, ft <sup>3</sup>	Soil Volume, ft <sup>3</sup>	Concrete and Soil Volume, ft <sup>3</sup>	Crater Depth, ft	Compressive Strength (f'), psi
1	18.2	10.8	29.0	3.25	4996
13	28.0	12.3	40.3	3.17	7534
Average	23.1	11.6	34.7	3.21	

Both tests were conducted on adjacent panels of the same slab, base, and subgrade thickness from which the model thicknesses were determined using cube-root scaling.

Table XII

COMPUTED SCALING FACTORS FROM MODEL STUDY

		Concr	ete Vo ft³	olume,	Soi	Soil Volume,		Concrete and Soil Volume, ft <sup>3</sup>			Crater Depth, ft		
W, 1	W, gm	V	V 2	m*	V	V <sub>2</sub>	m*	V	V	m*	D <sub>1</sub>	D <sub>2</sub>	n
681	17.5	23.1	0.91	1.53	11.6	0.20	0.67	34.7	1.10	1.28	3.21	0.98	3.09

 $W_1/W_2 = m(V_1/V_2)$ , where m = 1.0 if there is no distortion.

The above scaling factors were obtained from the results of only two small-scale model tests (9 and 10). However, this limited feasibility study indicates that, if large-scale models (say 1/2 scale instead of the 1/5 scale used here) were used and more tests were conducted with various depths-of-burst and charge sizes, reasonable correlation between the prototype and the model tests may be expected.

# SECTION IX

#### CONCLUSIONS AND RECOMMENDATIONS

#### CONCLUSIONS

Visual observation in the field revealed that there were three types of craters caused by the C-4 charges in the depth-of-burst range tested. These were as follows:

Type I 
$$(D/R \le 1.0)$$

These were shallow depth-of-burst craters of approximate hemispherical shape; the pavement beyond the crater was not appreciably heaved or cracked; and the ejecta was widely scattered with small concrete pieces, some of which measured a maximum 2 ft.

Type III 
$$(D/R > 5.0)$$

These were deep depth-of-burst craters; there was no apparent crater and very little ejecta; a cavity was formed in the subgrade; and the overlying concrete slab was extensively heaved with the resultant radial cracks creating huge wedge-shaped pieces.

Type II 
$$(1.0 < D/R \le 5.0)$$

These were intermediate depth-of-burst craters which exhibited some of the characteristics of both types I and III craters; the apparent crater shape was conical with ejecta of intermediate size (between types I and III); and the true crater was bulb-shaped at the bottom with the frustum of a cone at the top.

This distinction of crater types is important in considering the possible repair techniques for bomb damage.

A general purpose bomb, usually detonated near the surface, will yield a type I crater; types II and III craters result only from detonation of special weapons having the capacity to penetrate deep beneath the pavement system. The relationships between crater parameters for the maximum damage depth-of-burst and the equivalent bomb sizes (fig. 54) will be valid only for special situations where the depth-of-burst is optimized; this optimization can be realized only when special cratering weapons are used. The relationships between the different crater damage conditions at shallower depths are

also shown in figure 54; these curves should approximate the damage that can be expected by near-surface detonation (general purpose bombs).

The true crater quantities from Fort Sumner were, in general, smaller than those from Hays for all C-4 charges. This was due to the difference in soil media at the two test sites, i.e., silty sand at Fort Summer and silty clay at Hays. This finding is corroborated by similar crater data from reference 1 in which the crater quantities in pavement systems in the clay subgrade were over twice those in the silty sand subgrade. Pavement systems whose subgrades have a high percentage of clay will generally be damaged more than pavement systems with a lower clay content.

The concrete area in types II and III craters to be repaired because of cracks and heaves was a major part of the total concrete repair area. In general, the concrete repair area is maximized at a deeper depth-of-burst than are the other crater damage quantities.

The concrete area to be repaired was slightly larger for the 8-in.-thick concrete than for the 11-in.-thick concrete slabs for both the 5- and 15-1b charges. In general, the thickness effect is less significant with increasing charge size.

The volume of available material on the surface (i.e., the ejecta and concrete repair volume less the concrete crater volume) for all bombs tested at lays was in general much larger than the apparent soil crater volume; hence, this material can possibly be used for backfilling the crater.

Apparent crater volumes for the bombs tested at Hays were found to be well predicted by the cone formula using the apparent crater height and the apparent crater radius. This relationship is useful for calculating volumes of backfill material needed so that the material can be transported from elsewhere.

Similitude analysis, using the crater results from the 25-1b charge at Hays as the prototype data and the results from the 5- and 15-1b charges as the model data, showed that the scaling factor varied rather widely for scaling the maximum damage depth-of-burst and the true surface crater radius. A similar analysis of the crater volumes showed a large distortion. This was expected since the existing pavement structure did not satisfy the similitude requirements for the different charge sizes. This analysis revealed that

cube-root scaling to determine the depth-of-burst for a given pavement system is not satisfactory.

The limited feasibility study showed that consistent data were not obtained with very small charges (such as 10 gm) probably because the materials of the various parement layers were not scaled properly. If a smaller geometric scaling factor (say 1/2 scale) is used, it will be easier to scale down the material sizes.

Considering all the data obtained from the field tests at both sites, the authors feel that both simulation techniques using uncased C-4 charges and static detonation at a given depth-of-burst are valid experimental tools for defining crater damage parameters.

### RECOMMENDATIONS

Analysis of the crater data obtained from the full-scale field tests reveals that further research is needed to establish the relationship between each dependent variable (i.e., concrete repair volume, true crater depth, etc.) and the independent variables such as the charge size, and the pavement and soil properties. Although empirical relationships between the dependent variables and a few independent variables such as the charge weight and depth-of-burst have been established in this report, it would be desirable to determine the significant effect of each independent parameter of the system on the crater damage quantities by a more formal method based on statistical analysis (i.e., regression analysis). Such an analysis will, hopefully, point out which of the independent parameters are not important and, therefore, could be excluded from further examination in crater studies.

The feasibility study of modeling pavement cratering including the literature survey performed at CERF indicates that a study using larger models (i.e., 1/2 scale) may yield important information regarding the scaling and distortion factors for the various charges in different pavement systems.

#### APPENDIX I

### FORT SUMNER SUBSURFACE EXPLORATION DATA

Laboratory tests were conducted on soil and concrete samples from the test site in order to analyze the pavement crater data from the full-scale field tests at Fort Summer. Figure 62 shows the locations on the test section from which these samples were taken.

## 1. SOIL TESTING

Five test borings were conducted with a 2-in. ID, 2.5-in. OD California-type sampler with a 4-in. segmented brass liner. The sampler was dynamically driven by a 140-lb hammer with a 30-in. freefall. The blowcount, the dry density,  $\gamma_{\rm d}$ , and the moisture content, w, were obtained every 2.5 ft down to a depth of 20 ft. Bag samples were also taken at each 2.5-ft interval during the boring operation for laboratory testing of the specific gravity,  $\rm G_{\rm g}$ , and the Atterberg limits for soil classification.

Three trenches were dug adjacent to the test section at stations S16, N15, and N44. Balloon density and moisture content were taken at 2.5-ft intervals down to a depth of about 14 ft. Bag samples, also taken at each 2.5-ft interval, were tested in the laboratory for the specific gravity,  $G_{\rm S}$ , and the Atterberg limits for soil classification.

Three slabs (stations S11E2, S12E4, and N44E6) were cut out and balloon density, moisture content, and bag samples were taken directly under the slabs. The same tests were also conducted at 2.5-ft and 5-ft depths at stations S12E4 and N44E6. The results of these soil tests are given in table XIII.

### 2. CONCRETE TESTING

Three concrete specimens were received from the test site (stations S15, N13, and N44). Four cylinders, each approximately 4 in. in diameter and 7 in. long, were core drilled from each of these samples. The ends of the cylinders were then milled down.

The density,  $\rho_c$ , was first determined. Sonic velocity tests were then performed using sonic testing equipment and a 300-1b compression load to obtain good contact at the ends. Uniaxial compression tests were performed on the cylinders to determine the ultimate compressive strength of the concrete,  $f_c^1$ ,

from which the modulus of elasticity,  $\mathbf{E}_{\mathbf{c}}$ , was computed (ref. 12). These test data are given in table XIV. The concrete strengths reported here are probably on the high side because of the small cylinder size. (The concrete strengths given in the literature were obtained by testing 6- x 12-in. cylinders.)




Figure 62. Location of Borings (Fort Sumner)

Table XIII
SOIL TEST DATA (FORT SUMNER)

Depth, ft	Unified Classification	Υ <sub>d</sub> , pcf	N/ft	G <sub>s</sub>		ture Co	ntent, %
	St	ation S11	E2Un	der S1	ab		
1							
	SM-SC		) F.A. 11	2.63	<u> </u>	þ	
	St	ation S12	21:4Ur	ider S.	lab	<u> </u>	<del></del>
1	01.00			2 66	.5		
2	SM-SC			2.66	7	0	
3 —		111			þ		
4							
5 —		109			-		
	Sta	tion N44I	1	ler Sla	l	<u> </u>	
1 —	SM-SC			2.61	<u>Р</u>	0	
2 —		0.6					
3 —		96			7		
4		•					
5		108					
		Station	S167	rench			
1							
2 —							
3 —	SC	101		2.66	4 <del>-</del> Ç-	) )	
4					/		
5 -		105		0.45			
о —	SM	105		2.67	0 40		
7 —							
8 —	SM	105		2.69	þ	NP	
9 —		<del>-</del>					
10	SP-SM	121		2.66	4	NP	
11				2.00	/	***	+ •
11							

o Liquid Limit (LL) △ Plastic Limit (PL) □ Natural Moisture Content (w)

Table XIII (Cont'd)

Depth,	Unified Classification	γ <sub>d</sub> , pcf	N/ft	Gs	2	cure Conte	
	Stati	on S16T	rench'	(Conti	nued)		
13	SW-SM	110		2.66	Q	NP	
14				ė.			
15-	CH	114		2.67		20-	
		Station	N15T	rench	I	<u> </u>	
1							
2							
3 —	SC	90		2.64	무 스	~	
4 —							
5 —	SM-SC	102		2.65	. Δ-o		
6							
7	SM	109		2.68		NP	
9 —	<u> </u>	1.02		2100	<del>-                                    </del>		
10-	SM	107		2.65	<u>,</u>	NP	
11-	X <sup>1</sup>	107		2.05	7	INP	
12-				9 (			
13	SP-SM	115		2.66	<u> </u>	NP	!
15							
	SW	131		2.68	<u></u>	NP	
ļ <sub>1</sub>		Station	N441	rench			
2							
3 —	SC	93		2.68		<b>-</b> -∘	
5							
$\begin{vmatrix} 3 \\ 6 \end{vmatrix}$	SM-SC	116		2.74	<b>₽</b> ~~	<b>&gt;</b>	

o Liquid Limit (LL) △ Plastic Limit (PL) □ Natural Moisture Content (w)

Table XIII (Cont'd)

Depth,	Unified	$\gamma_d$ ,	N/ft	G <sub>s</sub>	Moistu	re Conte	nt, %
Ît	Classification	pcf		s	2	:0 I	40 · I
	Stati	on N447	'rench	(Conti	nued)		
8 —	SM	108		2.70	7	NP	
9 —	<u> </u>	100		2.70	7	711	<del> </del>
10-							<u> </u>
11—	SP-SM	107		2.62	<u> </u>	NP	ļ
12—							
13	SW	125		2,67	4	NP	<u> </u>
14							
15	<del></del>						
	CL	113		2.72	40		<u> </u>
<u> </u>	S	Station S1	.6E1E	oring	1		<del></del>
1 —		105	27				
2 —	SC	127	23		47	<u> </u>	
3 —	SM-SC	99	8		Δ0	7	
4 —						-	
5 —	SC	102	6		<u> </u>	0	
6 —		102			$-\mathcal{T}$		
7 —							
8 —	SP	103	19		<u> </u>	NP	<u> </u>
9 —							
10	SW	113	28		4	NP	
11							
12—	CI CII	00	1.7			<u></u>	
13	CL-CH	99	17			7	
14-						/	
15	CL	113	23		户		þ
16-17-					T		
18	SC	122	18		Δ0	<b>D</b>	
				<u> </u>			1

o Liquid Limit (LL) △ Plastic Limit (PL) ☐ Natural Moisture Content (w)

 $\mathcal{H}$ 

Table XIII (Cont'd)

Depth, fit	Unified Classification	γ <sub>d</sub> , pcf	N/ft	G <sub>s</sub>		ture Cont	ent, % 40
	Statio	n S16E1	Boring	1 (Cc	ntinued)		
20—							
20	CIL	106		20	<u> </u>	<b>-</b> 0	
<u></u> ,		Station S	S2E2B	oring	2		
1 _							
2	SM-SC	124	13	2.65	74	0	
3 —	SM-SC	97	6	2.74	<u> </u>		
4 —							
5 —							
6 -	SM-SC	107	10		<u> </u>	<u> </u>	
7 —							
8 —	SM-SC	102	9		þ		
9 —							
10-	SP-GM	102	41			NP	
11-	3r - 3vi	102	41			141	
12—						<u></u>	
13-	CH	107	21			<u> </u>	0
14-							
15	SC	119	17	2.62	<b>μ</b> Δ	-	
16—					/		
17	ON CC	124	7.0			, , , ,	
18	SM-SC	114	19		7	NP	
19-							
20	SP	105	17		d	NP	
		Station :	N15E1	Boring	3		
1 —							
$\begin{bmatrix} 1 \\ 2 \end{bmatrix}$	SM-SC	116	14		<u></u>	0	
3 —	SC	112	7		<del> </del>	)	

o Liquid Limit (LL) △ Plastic Limit (PL) □ Natural Moisture Content (w)

Table XIII (Cont'd)

Depth, ft	Unified Classification	γ <sub>d</sub> , pcf	N/ft	Gs		ture Cont	ent, 40
	Station	n N15E1	Boring	3 (Co	ntinued)		
5 —	ML-CL	117	12				
6							
7	O.	224	7.2				<u> </u>
8	CL	114	12		7		
9 —							
11-	SP	106	16		Ŕ		
12—							
13	SP-SW	106	48		<del>                                     </del>		
14							
15-	SW	118	50		<del>                                     </del>		
16	<u> </u>				7		<del>                                     </del>
17-						ļ	
18-	ML	122	18		<del>7</del>		
19—					/		
20	SM	94	14		4		
	S	tation N3	2E1B	oring	4		
1 -							
2 —	CL	110	10		7		
3 —	CL	105	9		þ		
4 —							
5	SM	110	9				
6					<del>                                     </del>		
7		7.5	7.0		<u> </u>		
8 -	SM	113	10		+		
9 —							
10	SP-SW	114	40	2.65	<b>P</b>		

o Liquid Limit (LL)  $\triangle$  Plastic Limit (PL)  $\square$  Natural Moisture Content (w)

Table XIII (Cont'd)

		7			Moisture Content &
Depth, ft	Unified Classification	γ <sub>d</sub> , pcf	N/ft	S	Moisture Content, % 20 40
	Station	N32E1Bo	oring 4	(Cont	tinued)
12-		*			
13	SP	106	49	2.65	<del>                                     </del>
14					
15-	SW	116	38		
16-	On .	110	36		<u> </u> -0
17-	· · · · · · · · · · · · · · · · · · ·				
18	SM	109	18		<u> </u>
19-					
20-	CL-MI.	95	16		
	St	tation N4	E1B	oring :	5
1					
2	CL	113	40	2.74	<b>P</b>
3 —	CL	102	15		<del>                                     </del>
4 —					
5 —	CL-ML	99	11	2.71	
6					<del>                                     </del>
7					-/
8 —	CL	103	16	2.65	
9					
1.0	SP	117	53		¢
11-					
13-	SW	110	66		1
14-					
15—	CI CII	117	26		
16-	CL-CH	117	36		<del></del>

o Liquid Limit (LL)  $\triangle$  Plastic Limit (PL)  $\square$  Natural Moisture Content (w)

Table XIII (Concl'd)

Depth, ft	Unified Classification	γ <sub>d</sub> , pcf	N/ft	Gs	2	ure Conte 0 4	nt, % 0 
	Station	n N44E1	Boring	5 (Co	ntinued)		
18-	SM	101	43				
19—				2 (7			
21—	SM	110	34	2.63	占		
							:
						:	

o Liquid Limíz (LL)  $\triangle$  Plastic Limit (PL)  $\square$  Natural Moisture Content (w)

Table XIV .

CONCRETE TEST DATA (FORT SUMNER)

Sample	Station	Density $(\rho_c)$ , pcf	Sonic Velocity (c), fps	Compressive Strength (f' <sub>c</sub> ), psi	Modulus of ** Elasticity (E <sub>c</sub> ), psi
1 2 3 4 Average	S 15 E1* S 15 E3 S 15 E5 S 15 E7*	150.66 148.36 149.12 149.75	13,500 14,220 14,030 14,550	5,966 10,027 9,470 7,242 9,749	4,713,617 5,909,722 5,847,650 5,144,201 5,878,686
5 6 7 8 Average	N 13 E1* N 13 E2 N 13 E4 N 13 E6	152.95 154.35 153.60 151.28	14,080 15,100 15,700 15,080 15,293	6,119 11,317 11,615 11,618 11,517	4,876,258 6,731,460 6,769,626 6,619,093 6,706,726
9 10 11 12 Average	N 44 E1* N 44 E3 N 44 E5 N 44 E7*	149.61 149.56 150.51 150.48	13,110 15,290 14,500 14,550 14,780	9,271 10,823 8,754 10,663	5,814,349 6,280,655 5,701,032 6,286,985 6,089,558

<sup>\*</sup>Since pads E1 and E7 (fig. 2) were not tested with C-4 charges, these results were not used to obtain the average numbers given in this table.

\*\* $E_c = 33 \ \rho_c^{-1.5} \ \sqrt{f_c^{-1}}$ .

### APPENDIX II

# HAYS SUBSURFACE EXPLORATION DATA

Laboratory tests were conducted on soil and concrete samples from the test site in order to analyze the pavement crater data from the full-scale field tests at Hays. Figure 63 shows the locations on the test section from which the samples were taken. In addition to these tests, in-place densities were obtained from the crater wall, the thrown-out material, and the fallback material of some of the bomb craters.

### 1. SOIL TESTING

The samples were furnished in Shelby tubes. The results of these soil tests are given in table XV.

Table XVI summarizes the in-place densities taken from the crater wall, the thrown-out material, and the fallback material of some of the MK-81, MK-82, and M-117 bomb craters. Either sand cone or balloon density tests were conducted.

# 2. CONCRETE TESTING

Concrete specimens were received from three stations at the test site. Cylinders, 4 in. in diameter and approximately 8 in. long, were core drilled from the specimens. Each cylinder was milled down to approximately 7.5 in. The density,  $\rho_{\rm c}$ , was first determined. Sonic velocity tests were then performed using sonic testing equipment and a 1200-1b compression load to obtain good contact at the ends. Uniaxial compression tests were performed on these cylinders to determine the ultimate compressive strength of the concrete,  $f_{\rm c}'$ , from which the modulus of clasticity,  $F_{\rm c}$  was computed (ref. 12). These test data are given in table XVII.




Figure 63. Location of Borings (Hays)

Table XV SOIL TEST DATA (HAYS)

Depth, ft	Unified Classification	γ <sub>d</sub> , pcf	N/£t	G <sub>s</sub>	Moisture Content, % 20 40
		Stati	ion 2+8	32	
1 - 2 -					
3 -	CII	98		2.63	<u> </u>
4 -	CL	98		2.69	4)
6 -	CII	113		2.72	φ <u>υ</u>
		Stat	ion 4+	90	
1 -	CII	95		2.72	4-7
3 -	CL	104		2.69	
5 -	CL	103		2.74	
6 7 -	Cil	105		2.73	۵۵
		Stat	ion 18	+70	
1 -	aı	96		2.68	7
2 -	CH	103		2.69	<u> 2</u>
3 - 4 - 5 -					
6 -	CH	98		2.70	4
8 - 9 -	Cl	109		2.67	0-0
10 -					

o Liquid Limit (LL)  $\triangle$  Plastic Limit (PL)  $\square$  Natural Moisture Content (w)

Table XV (Cont'd)

Depth, ft	Unified Classification	γ <sub>d</sub> , pcf	N/ft	G <sub>s</sub>	Moisture Content, % 20 40					
<u></u>	St	ation 18+	70 (Co	ntinue	d)					
13 — 14 —	CL	116		2.67						
14										
ļ	Station 23+00									
1 - 2 -	СП	98		2.66	7					
3 -	CL	100		2.66	<u></u>					
5 –	CL	96		2.69	<u> </u>					
6 -	CH	99		2.66						
8 <b>-</b> 9 <b>-</b>	Cl.	120		2.70	7					
10 -	CL.	112		2.73	0					
		Stati	ion 324	-48						
1 - 2 -										
3 — 4 — 5 —	CI.	96		2.71	<u> </u>					
6 -										
8 - 9 -	CH	111		2.68						
10 - 11 -										

o Liquid Limit (LL)  $\triangle$  Plastic Limit (PL)  $\square$  Natural Moisture Content (w)

Table XV (Cont'd)

Depth, ft	Unified Classification	γ <sub>d</sub> , pcf	N/ft	ថ្ង ទ	Moistu 2	ire Conter 0 4	1
	St	ation 32+	48 (Co	ntinue	:d)		
13 -	SN'			2.68	0	NP	
14 -	U1	<u> </u>		.2.08.			0
15 -							
16							
17 -							
18 -	CH	111		2.76	C	يح——حر	
		Stati	on 44+	51			
1 -							}
2							
3 -					-		
4 -							
5 -		0.0		2 77		<b>8</b> 0	
6	CL	99		2.73			
7 –							
8 - 9 -	CL	103		2.70		4)0	
10 -						/	
11 -			<u> </u> 		/		
12 -					/		
13	CI	117	<u> </u>	2.71	Ø		
14							
15					/	!	
16							
17 -				<u> </u>			
18 -					6		
20 -	SW	112		2.65		NP	
20				<u> </u>		<u> </u>	

o Liquid Limit (LL)  $\triangle$  Plastic Limit (PL)  $\square$  Natural Moisture Content (w)

Table XV (Concl'd)

Dept ft	h,	Unified Classification	γ <sub>d</sub> , pcf	N/ft	G <sub>s</sub>	Moisture Content, % 20 40				
			Stati	on 51+	17					
1	-									
3		CH	99		2.69	Δ <u></u>				
5		CH	100		2.69					
6 7		CH	95		2.68	s-b				
			Stat	ion 55-	·13					
		CII	104		2.63	<u>~</u>				
3		CL	99		2.68	۵۵۰				
5 6		CL	98		2.66	٥				
7		CH	98		2.64	d-s				

o Liquid Limit (LL)  $\triangle$  Plastic Limit (PL)  $\square$  Natural Moisture Content (w)

Table XVI
SUMMARY OF IN-PLACE DENSITY TESTS (HAYS)

Shot	Depth-of- Burst, ft	Cylinder	Type of Density Test	Density, pcf	Comments
			MK-81		<u> </u>
75	10	1 2 3 4 5 6 7 8 9 10 11 12 - 13 14 15	Sand Cone	123.14* 114.89 105.61 110.61 107.37 116.76 111.81 109.10 112.36 120.95 110.03 120.86 131.09 107.08 121.42 119.32	Fallback  —Crater Wall  —Apparent  Crater Wall
	I		Mr82	L	<u> </u>
81	12	1 2 3 4 5 6 7 1 2 3 4 5 6 7 8 9 10 11	Sand Cone Ballcon Sand Cone	118.37 105.87 107.54 87.40 118.91* 123.16* 115.27* 121.80 115.32 108.81 120.18 87.23 114.26 106.03 111.10 104.50 111.04 98.00 127.84	Fallback  —Fallback  —Ejecta —Crater wall
	,		M-117		
90	15	1 2 3 4 5 6 7 8 9	Sand Cone Balloon	123.63 124.22 126.90 120.64 122.42 121.24 128.52 122.89 131.06	—(rater hall

<sup>\*</sup>large chunk inside crater.

Table XVI (Concl'd)

Shot	Depth-of- Burst, ft	Cylinder	Type of Density Test	Density, pcf	Comments
		M-	·117 (Continue	ed)	
91	12	1 2 3 4 5 6 7 8	Sand Cone	91.22 115.49 110.49 120.17 96.50 128.20* 111.74* 118.94*	-Fallback
92	15	1 2 3 4 5 6 7 8 9 10	Sand Cone	88.94 91.04 95.36 114.89 96.05 91.15 94.10 112.23 90.98 109.30 117.84 120.49 121.81	-Fallback -Ljecta -Crater hall
93	18	14 14 1 2 3 4 5 5 7 8 9 10 11 12 13 14	Sand Cone  Balloon	107.85 107.69 115.82 120.18 113.78 122.85* 114.00 120.39 119.54 115.86 118.32 117.69 119.50 118.40*	-Fallback -(ruter Wall
95	21	1 2 3 4 5 6	Sand Cone Ealloon	95.19 126.63 92.62 105.20 104.40 118.50	—Fallback —Large (hunk `utside (rater

<sup>\*</sup>Large chunk inside crater.

Table XVII

CONCRETE TEST DATA (HAYS)

Sample	Station	Density (p <sub>c</sub> ), pcf	Sonic Velocity (c), fps	Compressive Strength (f' <sub>c</sub> ), psi	Modulus of Elasticity (E <sub>c</sub> ),* psi
1 2 3 4 Average	5+00	145.92 145.41 147.43 150.19 147.24	17,539 17,488 17,586 19,195 17,952	9,168 8,817 8,356 12,892 9,808	5,567,460 5,435,054 5,396,640 6,898,074 5,824,307
1 2 3 Average	28+00	147.49 147.14 149.37 148:00	17,762 18,316 18,955 18,344	8,611 10,186 10,465 9,754	5,484,490 5,941,698 6,164,308 5,863,499
1 2 Average	52+00	146.05 147.31 146.68	18,077 17,584 17,830	9,768 11,937 10,853	5,756,539 6,446,574 6,101,557

 $<sup>{}^{\</sup>star}E_{c} = 33 \rho_{c}^{1.5} \sqrt{f_{c}^{F}}.$ 

#### APPENDIX III

#### FORT SUMNER CRATER DATA


	Page
5-1b Charge, 7-Inch-Thick Concrete	120
15-1b Charge, 7-Inch-Thick Concrete	124
25-1b Charge, 7-Inch-Thick Concrete	130


Table XVIII


DAMAGE QUANTITIES FOR C-4 CHARGES (FORT SUMMER)

50-7 50-7 50-7 50-7 50-7 50-7 50-7 50-7	T i	111	- -		~	Craces	~	Crater	And a	end 50	1	27.0			dice	-			-
5871 Ma 25812 Ma 25812 Ma 25812 Ma 25812 Ma 25812 Ma	T	111	-			Crates	74.	Croter											
NSB 3 NSB 3	12	E		157	_					-	m	Depth	~	١.٠	~	٠.	**	7	~
NSB 3 NSB 3	2882	12		137		FAOUR												_	_
MANU IN		1 0			ינג	20	×	52	14	337	137	3.8	3.8	7 50	2 54	7 9	779	25	254
MANU IN	<u>بر</u>		22.	117	237	25	27	12.	*	1.5	144	1.3	3 55	33	3 42	1:3	7 10	1.0	34
		1 2	25	117	727	in u		1 2	*	140	159	1.00		2 1		1 ; ; ;	, m	1:2	1, **
59/64 37	1 55	1 6 34		117	1	· 56	12	1 50	122	147	.,,	1 1 5 56	1.2			, , ,,	1 + 44	1 2 99	1 12
45-25 M	1 2	1 :3:		13	137	20.00	39	1 2	×	130	150	::		1:2		1 :::	1	1:2	1.50
93 1 15 1000 10	1 3	13		127	117	20	aί	2	a	137	19	18		9 43		1:3		15.5	1.5
MALE N	1 3	1 :21		. 127	w		16	# 1	15	332	11.	33	6 10	:::	0 50	;;	7 99	12	1.50
	.,		-		_			15 30	0	-			-		*		*****	٠	
5245	7 5	1 18	_	15		*		*		200		4.0	_	1.0	1	1	_	130	_
NAME OF THE PARTY OF	1 :	22.2	N	13	134	54 A7		1.2	*	385	397	1.5	3 **	34	*	1 : 3	* **	1;;	2 90
442 15	1 2							íū				4 10	į	1 7 %	į		ł		t
2014	1 5	2	27	: :	^	24.5	141	145	129		•	:::	. "	1 3		1:	١.	125	
444 115		1 2	*	150	197	94		316	NI.	242	243	4 #3	4 63	\$ 27	57	8	9 25	1 22	1527
was I i	1	8 >e l		252	200		344	29Z	223	700	346	150	500	2 72	6 50	12.2	la≆.≫		le sa i
25	1 2			233		201		274		307		:::		2	}	" "	1	12	1
172	1 24	410	•	201	241		291	440	576	55%	479	7 37	* **	7.5	10.05	10 72	mm	7 75	1 5
MOZ IL	1 %	1:5		395	204	107	- 7	207	4	594 302 344	270	1.0	9 22	1 2	1 . m	100 Ft	1 20 45	12	2.3
N'W 15	1.5	1.0		205				1 11	1	173	٠.	12.05		100	ł	34 57	· .	2 07	
Mary M	1 54	1 3 3	4 30	115	127	*	**	-	е	344	578	55	**	1 6 7	6 00	1	7 77	14	2 35
								75-0	Cherry										
1674 es	1 4	1 #	,	340	201	15		14		345		5 67		1%		11 %	_	5 %	i –
NY2 144	1 5	1 5	<b>"</b>	347	e)	93	124	152	199	315	354	\$ 53 5 23	2 24	24	1 5 27	1: 5	30 72	7 34	6 27
M V4 17	1 :	1 : 1		244	,,,	130	20.7	294 344	300	345 606		× 2	. «		I	13 14	1	6 14	l
ana ta	* **	140 1	- "	150		N+1	L ""	5%		439		7 67	• "	:3	1	33 84	7 0	;:	
MAN 145	1 22	1 2		**	20		١. ١		١.		. :		١. ١	\$ 53	1	22	ا را	1:	1.
	203	ű		133	-							•			1	7,00		•	


"Sala Jan. reservi net plorted









5-1b Charge, 7-Inch-Thick Concrete





5-1b Charge, 7-Inch-Thick Concrete (Cont'd)




5-1b Charge, 7-Inch-Thick Concrete (Cont'd)










15-1b Charge, 7-Inch-Thick Concrete (Cont'd)






15-1b Charge, 7-Inch-Thick Concrete (Cont'd)






15-1b Charge, 7-Inch-Thick Concrete (Concl'd)



25-1b Charge, 7-Inch-Thick Concrete



## APPENDIX IV

# HAYS CRATER DATA

		Pag	e
5-1b Ch	arge, 8-Inch	-Thick Concrete 13	4
5-1b Ch	arge, 11-Inc	h-Thick Concrete	1
15-1b Ch	arge, 8-Inch	-Thick Concrete 14	3
15-1b Ch	arge, 11-Inc	h-Thick Concrete	9
25-1b Ch	arge, 8-Inch	-Thick Concrete 15	5
MK-81 (2	50-1b Bomb),	11-Inch-Thick Concrete	8
MK-82 (50	00-1b Bomb),	11-Inch-Thick Concrete	0
M-117 (7	50-1b Bomb).	11-Inch-Thick Concrete	2

Table XIX
DAMAGE QUANTITIES FOR C-4 CHARGES (HAYS)

		_	C stef Years, 10°										Year Craf	4	Central Page 11			
944		**	Control			1 30		Committee and Sand			marks (2)	•				No Bryts		
in state	1		6000	4	Arres	A.	Outer   for		Created for   Suppose   hog			Better My		1 12		**	4, 124	
-	5-50 though, I Such thick Law Arts																	
274/8 308/4	2	:	7	,,	170 545 19°	3,84	_	28	_	,	_	, ,	121		12 342	::	, .,	15 14
307	2	3	7		733 173 173 173	373	10	٠,	3528256	,,	112	200	[ [ ]	127	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	::	5 CE	12 12 12 13 14 13 15 15 15 15 15 15 15 15 15 15 15 15 15 15 15 15 15 1
344,1 34 /14		×	33	45	173 265	tes	44	*	147	**	20.24	***	150	165	120	::	• >>	1
24.7	5	2	*	"	10"	184	4	R3	ŝ	139	248 25°	26"		54	1300	12	* 52	14 24
308/4 5"3/6 55/79 8 P 2"2/6 36/8 36/8 36/79 362/9 25/6 25/6 25/6 25/6		1	4	"	14	4.3	20 20 20 20 20 20 20 20 20 20 20 20 20 2	•2	15	1	(4) 146	754 764	iğ,	×	2000	175	9 04	1 2
204/5 270/5 2/5	27842251823CERRAR	***************	***************************************	1 76	5444444444	399 391 378	1	3 7 2	TERMEN SAN	54 30	<b>子是在在原序已来来完全是有意思其他的记录</b>	239	9 94 9 95 9 98 4 95 4 95 5 10 5 10 5 10 6 60 6 95		3 ) s 3 ) s 3 ) s	100	9 55	10 . s
<u> </u>						_				n.h 33		_		_	,	فتنت		
3477	19	3	54	94	14	196	55	55	149	101	255	255	141	м	4 33 0 33		17	413 413
20/7 20/7 20/7	26222	2228	3350	335 9		200 200 203 203	27 28 28	2 2 2	15 25	15 15 15	255 270 254 262 270	255 260 254 286	3388	3 8 2	1313	3		12 12
199/1	144	40	- 53		200			200	1.0	_	274	_	\$ 50 (	~	*n  ' "	1 9		4 21 - 4
N-	77	20	34		.73				1112	_	_	_	491	-	4.34			( ×)
8/8 80/9 85/18 10/8 17/5 8/18 18/1 81/4 81/4 81/4 81/4 81/4 81/4	ar deed y	3227233335	*******	s	ATTENESTS.	<b>3</b> 72	74 17 33	•	526825628250ac	"	***************	207	127 128 128 128 128 128 128 128 128 128 128	*	* , ,	18:1:3:	7 65	1 30 5 40 1 30 5 40 1 30 5 40 1 30 5 40
ĽŽ.	12	3	72	**	2%	æ.	15	140	200	2,19	*45	403	:::	*	12	10 5	TO SA	5 95 5 W
1	1	3	:		-	'	ii.		2		3	ì			0.40			i s as l
252/4	*********	50	**	4# • #5	2242	190 ZzX	SEEEE	149 138 5M	2%	110	54	324 344 135	100 100 100 100 100 100 100 100 100 100	7			10 45 10 45 10 50	4 87 5 47 3 96 3 40 6 70 6 70 2 75 3 78 3 78 3 17 2 97 3 97 3 97 3 97 3 97 3 97 3 97 3 97 3
12/10	16	10	4 15	1 1	226	140	13		썙	276	533	365	4.5	- 1		2 . S	20 50	2 75
94/14 94/14 94/14 14/14		22825	4 95 4 95	* *5	10.		134 308	204	120	"	-	l**	1851"	R		1 12	• "	\$5 °
300/14 200/14	13	110	4 95 4 95 4 95 4 95	• 95	10. 10. 10.	195	103 203	95	138 265 165	*	242 301	746	11.3	*	100	* AB	74	\$ @ 1×
	_			-			_	70.0	_	~ 1 10		705.4		_				
10/6 12/7	[1]	10	94		216	210	75 20 10 11 11	ю	325 194	170	305	1015	:51	9	12 14	12	14	(C) en
32/7 14/4 24/4	**********	19933784875	61 61 86 110	,,	28.52.44	24.	15	146	ihe i de e e e e	213	\$122355E	٠.	556 4863882	144	\$ 50 KM	12	9 34	12 441 4 15 5 14 5 45 5 16 1 40 7 7 1 10 7 1 10 7 1 10 7 1 10 7
20/4	1	×	42	79	3.	43	1 255	242	155	20	5/5 154	***	186	14	5 M	1.0	9 19	\$ 15 m
30%	1.0	3	a	1 14	/ <b>**</b>	24	305	104	100	105	383	381	:::	15	\$ 50 0 30	* 157	9 M	30 / 2
33555555555555555555555555555555555555	lii l	×	12	1.29	148 248	(%)	123	14	110	112	177	146	22.	45	12.00	6 24	***	18 1.15 18 2.71
W.	14	IM IM	13	1 29	248 272	19	300	116	107	117	355	354	1200 11	71	1: 00	14	9 12	30 27
				_		_	35	_		an.		_		_			_	
144/5 14 / 9 316/11	100	Rock	105 S C C	101	25.25	346	8	A2	4	34)	\$	750	100		6 87 6 87	11 2 2 3	10 SA 11 26	4 77
	15	95	105	† '	437		120		405 177	1	27.8		20 15	- 1	22	1 2 3 3 A 2 A 2 A 2 A 2 A 2 A 2 A 2 A 2 A	1	13
1100 1100 1100	13	20	1 3	00	30	٠.,	100	153	1.0	154	175	5070	1117	*	6 41	22 6	13 24	1.9 3 11
1 411	777758.5	12.	29.50	• "	155 265	10	#07 #41 #01	134	145	114	422 202	m3	13 50 13 50 13 50 13 50 13 50	. "5	ig.,,	10.40	1.2 SA	La Li Li Va
	-	-		-		-	·	-						v Ca.				

Table XX


DAMAGE QUANTITIES FOR EXHBS (HAYS)


	- 1	1				Yes	Center							rent Crater	
91	·				Sec. 6	7		Greter	(reter	Reign	.0	-	Teluty,	W	
SACAT PAR		*	Con	Serpeur	14-1	Crater	and Got 3 Refueld	Popula Popula				Epecta	Crates	Approximate (mage <sup>2</sup>	Septh Septh
							A 61 4	10 10 200	,						
583 582	* 30 € 3 - x	******	5253238	1:50 1:76 2:40 1:33 1:05 7:20 2:05	7 457 205 3 40 4 68 4 68	122274	2 8 3 5 8 B	798988 75227721	12.70 14.86 12.00 12.00 12.50 12.50	******	1111111	20 888.83	\$22,922.5	1153¥3Z	10 K C 2 K C
							W 12 (	40 Ib head	*						
555 F53	2 2 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	-222252	808 8340 973 986 971 880	7749 2742 0424 2933 1740 2177 2021		Eğrığır	38:13:1	7311 51:	4 8 8 4 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	225222	11 × 11 × 11	22,52,583	14.2.5.2.5.2.2.5.2.2.2.2.2.2.2.2.2.2.2.2.	EST TESS	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
							*117 (	50 19 Aus	)						
141, 7 151/7 167/7 167/7	N 25 25 25 25 25 25 25 25 25 25 25 25 25	111111111111111111111111111111111111111	22 12 12 12 12 12 12 12 12 12 12 12 12 1	75 A 25 A 36 A 36 A 36 A 36 A 36 A 36 A 36 A 36	31.23	1 2 1 2 2 3 2 3 1	1 51 6 2 2 3 2 1 2 2 3 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3	81874 811874	F. 24 20 77 20 20 20 20 20 20 20 20 20 20 20 20 20 2	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	41.22	1275 1514 1495 1506 1357 618 2043	2774 30 4 3225 35 1 2540 1344 1340	900 900 201 100 100 100 201 310	3 4 4 5 7 5 7

merings value pt peed depth-of hund


so Minusk tuern fajj pina


To the state of th







5-1b Charge, 8-Inch-Thick Concrete (Cont'd)









S-1b Charge, 8-Inch-Thick Concrete (Cont'd)







5-1b Charge, 8-Inch-Thick Concrete (Concl'd)





5-1b Charge, 11-Inch-Thick Concrete




5-1b Charge, 11-Inch-Thick Concrete (Concl'd)










15-1b Charge, 8-Inch-Thick Concrete (Cont'd)






15-1b Charge, 8-Inch-Thick Concrete (Cont'd)







15-1b Charge, 11-Inch-Thick Concrete




15-1b Charge, 11-Inch-Thick Concrete (Cont'd)




15-1b Charge, 11-Inch-Thick Concrete (Cont'd)




15-1b Charge, 11-Inch-Thick Concrete (Cont'd)




15-1b Charge, 11-Inch-Thick Concrete (Cont'd)




15-1b Charge, 11-Inch-Thick Concrete (Concl'd)







25-1b Charge, 8-Inch-Thick Concrete (Cont'd)




25-1b Charge, 8-Inch-Thick Concrete (Concl'd)




MK-81 (250-1b Bomb), 11-Inch-Thick Concrete







MK-82 (500-1b Bomb), 11-Inch-Thick Concrete



MK-82 (500-1b Bomb), 11-Inch-Thick Concrete (Concl'd)







## APPENDIX V

## MODEL STUDY DATA


		Page
Test 2:	11.3-gm Charge	165
Test 3:	9-gm Charge	166
Test 4:	11.5-gm Charge	167
Test 5:	13-gm Charge	168
Test 6:	7-gm Charge	169
Test 8:	15-gm Charge	170
Test 9:	17.5-gm Charge	171
Test 10:	17.5-gm Charge	172




Test 2: 11.3-gm Charge




Test 5: 9-gm Charge




Test 4: 11.5-gm Charge




Test 5: 13-gm Charge




Test 6: 7-gm Charge



Test 8: 15-gm Charge



Test 9: 17.5-gm Charge



Test 10: 17.5-gm Charge

#### REFERENCES

- Pichumani, R., and Dick, Jr., J. L., Effects of Small Cratering Charges on Airfield Pavements, AFWL-TR-70-66, Kirtland Air Force Base, New Mexico, December 1970.
- Vesić, A. B., and Barksdale, R. D., Theoretical Studies of Cratering 'Mechanisms Affecting the Stability of Cratered Slopes, Final Report, Project No. A-655, U.S. Army Engineer Waterways Experiment Station, Mississippi, September 1965.
- Chabai, A. J., Scaling Dimensions of Craters Produced by Buried Explosives, SC-RR-65-70, Sandia Laboratories, Albuquerque, New Mexico, February 1965.
- Johnson, J. B., and Fischer, R. L., Effects of Mechanical Properties of Material on Cratering: A Laboratory Study, U.S. Department of the Interior, Bureau of Mines, 1963.
- Moraski, L. K., and Feal, D. J., an Investigation of the Effects of Gravity on Crater Formation in a Commissionless Hedium, Air Force Institute of Technology, Wright-Patterson Air Force Base, Ohio, September 1965.
- Bivoky, D., Comments on a Paper by A. J. Chabai, "The Equivalence of Mass and Energy Scaling of Crater Dimensions," Journal of Geophysical Research, Vol. 71, No. 10, May 15, 1966.
- Saxe, H. C., and DelManzo, D. D., Jr., "A Study of Underground Explosion Cratering Phenomena," *Proceedings*, Symposium on Engineering with Muclear Explosives, Las Vegas, Nevada, January 14-16, 1970.
- Galbraith, B. G., "Not's Analysis of Small Explosion Cratering Events in pry Otters Sar!, M.S. Thesis, Air Force Institute of Technology, Wright-Patterson Air Force Base, Ohio, June 1970.
- Bessert, G. C., the Effects of Variation of Charge Size and Depth-offurst in Laboratory S its Instering Experiments in Sand, M.S. Thesis, Air Force Institute of Technology, Wright-Patterson Air Force Base, Ohio, June 1970.
- Carlson, R. H., and Newell, R. I., Ljecta From Single-Charge Cratering Explosions, SC-RR-69 1, Sandia Laboratories, Albuquerque, New Mexico, June 1970.
- M'Andrea, D. V., Fischer, R. L., and Hendrickson, A. D., Crater Scaling in Granite for Exist Changes, Report No. 7409, U.S. Department of the Interior, Fureau of Mines, July 1970.
- 4c + tendard Bat | | | | le dequirements for Reinforced Concret (ACI 318-63), American Concrete Institute, Detroit, Michigan, June 1963.

#### INCLASSIBILE

UNGLASSIFILD							
Security Classification		<del></del>					
	NTROL DATA - R		•				
Se taxaif -rion of title body of abatract and indexi to this Given tirely ACTIVETY (Corporate author)	ing arnotation must be		e overall report in classified) SECURITY CLASSIFICATION				
the Iric H. Wang Civil Engineering Research	arch lacility	Za. REPORT	INCLASSIFIED				
University of New Mexico	,	25 GROUP					
Albuquerque, New Mexico 87106							
REPORT TITLE		<del> </del>					
PAVIAGNT CRATERING STUDIES							
A DESCRIPTIVE NOTES (Type of report and inclusive dates)							
January 1971 through January 1972							
5 AC INCRESS (Free name, middle initial, seet name)							
Asbjorn Kvammen, Jr.; Raman Pichumani;	James L. Dick,	Capt, US	AF				
HIPORT DAYE	78, YOTAL NO.	F PAGES	75, NO OF REFS				
December 1972	18		12				
** CONTRACT OR GRANT NO 1-29601-72-C-0024	90, ORIGINATOR	S REPORT NU	MBCR(S)				
b PHOJECT NO	AFWL-TR-	72-61					
6834							
•	3b. OTHER REPORT NO(5) (Any other numbers that may be as this report)						
	this report)	this report)					
d							
TO DISTRIBUTION STATEMENT	1 1						
in tribution limited to US Government as	gencies only b	ecause or	test and evaluation				
(1 Pec 72). Other requests for this dockirtland AFB, NM 87117.	cunent must be	e lefelled	to Arma (DEA),				
I) SUPPLEMENTARY NOTES	12 SPONSORING	MILITARY AC	TIVITY				
TO THE MENT HOLES							
	AFWL (I		07117				
	Kircian	d AFB, NM	0/11/				
(Distribution L.	imitation Stat	ement B)					
The objectives of this research effort we	ere twofold:	(1) to de	fine the damage to ai				
the lidebacement systems caused by a wide:	range of C-4 c	harges an	d bombs when detonate				
at various depths below the pavement sur-	face (i.e., de	termine t	he extent of damage e				
nected from these explosives), and (2) to	o investigate	the feasi	bility of scaling pay				
ment systems and explosives in order to i	more economica	illy study	cratering effects on				
different pavement systems. The first of	biective was i	molemente	d by a series of test				
using 5, 14-, and 25-11/ C-4 charges plan	ced at various	denths u	nder pavement surface				
in the a adoned arrifields (Fort Summer a	and Have) and	three siz	es of bombs at the Ha				
test site. Damage such as the repair vo	limas tria ci	rater dent	he etc were plotte				
as a function of charge size and depth o	fabrice The	a times	f graters were found				
as a function of charge size and depth of the shallow depth of burst craters of hel	romourical ch	o cypes o	doon donth-of-buret				
craters with no apparent crater and litt	inispilerical Si	1010, (4) 1 (3) into	mediate denth-of-bur				
craters exhibiting some of the character	ictice of both	the chel	incurace adjust-or-bus				
craters exhibiting some of the character charles. The crater dimensions from For	totics of both	i the Shall be eilt co	harada) wara in				
character anneasions from for	Low cubaroda	for all of	ograde, were, in				
peneral, smaller than those from Hays (c tuck analysis was conducted using the te	ray subgrade)	tor arr c	emans (Haus) to assess				
Tubb analysis was conducted using the te	st data Irom T	ine C−4 CN	arges (navs) to ascer				

this if a scaling factor or a distortion factor could be determined. The study not field that the scaling factor varied widely when scaling the maximum damage depth-of furst, the radius of the crater at the surface, and the crater volumes. To accomplish the second objective, small-scale tests were conducted modeling the full-scale experimental test, performed at CLRF in 1969. This study also indicated variations in

UNCLASSIFIED